



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. _____
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Record of casing perforating	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 12, 1959, 19

Well No. 1 ^{Federal} is located 530 ft. from SW line and 2110 ft. from E line of sec. 35

SE/4 Sec. 35 25N 10W NMPH
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Blasi San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6762 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Perforate casing with Walex Super Dyna-Jets, 1/foot

5350' to 5370' --- 80 holes

5383' to 5401' --- 72 "

5395' --- 2 "
Total 154 holes

Electric Log measurements



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Welshire Development Company

Address 125 Petroleum Club Bldg.

Denver 2, Colo.

By [Signature]

Title Sec'y-Treasurer