## HNITED STATES

		Parm	П	pproced	١.	1			
		Budge	ŧ	Bureau	N				
١.	LEASE	DESIG		ATION A	ND	н	ATOLIA	ı,	NO.

(May 1963)	DEPAR		Budget Furent No. 42 R1424. 5. LEASE DESIGNATION AND BARRAL NO.					
(Pa not	SUNDRY NO	G. IF INDIAN, ALLOTTE	G. IF INDIAN, ALLOTTEE OR TRIBE NAME					
i.		7. UNIT AGREEMENT N.	7. UNIT AGREEMENT NAME					
WELL A WELL OTHER  2. NAME OF OPERATOR			1		East Bisti	East Bisti Unit		
					8. FARM OR LEADE NA			
•	Oil Company		· · · · · · · · · · · · · · · · · · ·	* 411 l				
3. ADDRESS OF C	PERATOR			IIIN &	9. WELL NO.	**		
1860 Li	ncoln Street,	Denver, Colo	orado \80	203" COM.	72			
4. LOCATION OF See also space	WELL (Report location e 17 below.)	10. FIELD AND POOL, O	R WILDCAT					
<ol> <li>LOCATION OF WELL (Report location clearly and in accorda See also space 17 below.)</li> <li>At surface</li> </ol>			``	OIL DIST. 3	Bisti Lowe	Bisti Lower Gallup		
	660' FEL & 1980' FSL Secti			25N 10H	11. SEC., T., R., M., OR BLK. AND BURYEY OR AREA			
	OOU FEL O	i 1900 PSF Se	ection 30	F-Z3N-IUW	20	•		
					Section 33			
14. PERMIT NO.	14. PERMIT NO. 15. ELEVATIONS (Show whether DF, 1			, RT, GR, etc.)	12. COUNTY OR PARISE	13. STATE		
		6723'	GR KB	6733'	San Juan	New Mexi		
16.	Check A	Appropriate Box To	o Indicate N	lature of Notice, Report, or	Other Data			
	NOTICE OF INT				QUENT REPORT OF:			
TEST WATER	SHUT-OFF	PULL OR ALTER CASIN	No.	WATER SHUT-OFF	REFAIRING	WELLS.		
FRACTURE TE		MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING C			
SHOOT OR AC		ABANDON*	X	SHOOTING OR ACIDIZING	ABANDONME			
REPAIR WELL		CHANGE PLANS		(Other)		-		
(Other)				(Note: Report resu	lts of multiple completion apietion Report and Log fo			
17. DESCRIBE PRO proposed v nent to thi	work. If well is direc	PERATIONS (Clearly stationally drilled, give s	ite all pertinen ubsurface loca	t details, and give pertinent data tions and measured and true vert	es, including estimated dat	e of starting ans		
This we	ell has reache	d the economi	c limit	and is no longer pro	ofitable to oper	ato		
				plugging as follows		ale.		
First P	'lug - 100' pl	lug across Gal	lup Zone	perforations 5323-	53661			
Second	Plug - 50' ir	side the 5-1/	'2" casin	g and 50' above when	re casino is sho	t in two		
Third P	lug - 150' ce	ement plug ext	ending d	ownward from above	the Fruitland Co	al		
		across the P						
Fourth	Plug - 100' p		of Ojo	Alamo Sand (unless	surface casing i	s set		
	10 sacks of c	ement in top	of surfa	ce casing with dry	hole marker	•		
						•		

18. I hereby certify the line foregoing is true and correct		
SIGNED CHAFULLE	TITLE District Operations Supt.	DATE June 10, 1971
(This space for Federal or State office use		
CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE