UNITED STATES DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)

GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-1366

6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.) Navajo-Uska-Ye-Nu-Yah 7. UNIT AGREEMENT NAME WELL X WELL OTHER East Bisti Unit NAME OF OPERATOR S. FARM OR LEASE NAME Skelly Oil Company 3. ADDRESS OF OPERATOR 9. WELL NO. 1860 Lincoln Street - Denver, Colorado

37 5 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* 10. FIELD AND POOL, OR WILDCAT See also space 17 below.) At surface Bisti Lower Gallup 11. SEC., T., R., M., OR BLK. AND SUBVEY OR AREA

Section 30-25N-10W 12. COUNTY OR PARISH 13. STATE

1980' FNL & 1980' FEL Section 30-25N-10W

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6612.5' GR

San Juan New Mexico

16.

14. PERMIT NO.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
EST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING WELL	
RACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT	- ;	ALTERING CASING	
HOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING	The second secon	ABANDON MENT*	X
EPAIR WELL		CHANGE PLANS		(Other)			
Other)				(Note: Report res Completion or Reco	sults of multipl ompletion Repo	e completion on Wel rt and Log form.)	1

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

All depths shown are from ground level.

7/16/71 MI & RU Aztec Well Service Unit. Pulled rods. Spotted cement plug 5140-5040'. Pulled tubing. Worked $4-1/2^{\circ}$ casing to free same. Rigged up blue jet and perforated 1534-1535' with 4 shots. Ran 2" tubing. Spotted cement plug 1535-1385'. Pulled 2" tubing. Shot casing off at 1117'. Spotted cement plug 1167-1067', 50' inside casing and 50' above casing stub. Pulled 4-1/2" casing up the hole. Spotted cement plug 760-660'. Pulled total of 36 joints (1120') 4-1/2" casing.

Spotted 10' cement plug in surface casing. Installed dry hole marker.

Completed P&A 7/22/71.

DIST.

18. I hereby certify that the foregoing is true and co	rrect	
SIGNED 6 2 Byles	TITLE Lead Clerk	DATE 10-26-71
(This space for Federal or State office use)		
APPROVED BY	TITLU	DATE