



SINCLAIR OIL & GAS COMPANY
501 LINCOLN TOWER BUILDING
DENVER, COLORADO 80203

February 3, 1966

WESTERN REGION

Mr. P. T. McGrath, District Engineer
United States Geological Survey
P. O. Box 959
Farmington, New Mexico

RE: No. 078479
Hannett Federal, Well #1
NE NE Section 25-25N-8W
San Juan County, New Mexico

Dear Sirs

Enclosed is a revised Notice of Intention to Abandon the captioned well. This revision is made to confirm my telephone conversation with Mr. Coles on this date, and to comply with the requirements outlined in Mr. E. C. Arnold's letter of February 1, 1966.


Very truly yours,


Ford Haskin
Area Supervisor

meb

Encls.

cc: Mr. E. C. Arnold
Astos, New Mexico



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. 072179
2. NAME OF OPERATOR Simola Oil & Gas Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME .
3. ADDRESS OF OPERATOR 201 Lincoln Tower Bldg., 1850 Lincoln Street, Denver, Colo.	7. UNIT AGREEMENT NAME .
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit 1st 48' 790' 1/4 North line and 790' 2/4 East line Sec. 25-35N-3E	8. FARM OR LEASE NAME Hammitt Federal
	9. WELL NO. 2
	10. FIELD AND POOL, OR WILDCAT Dallard Pictured Cliffs
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 25-35N-3E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 657' G.L.
	12. COUNTY OR PARISH San Juan
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*


(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well drilled in 1957 to TD 2250', 5-5/8" OD 2 1/2" casing set at 96', 5-1/2" 25.5' casing set at 2250', Pictured Cliffs perforated 2124' to 2190'. This well produced only 117 MCF during year of 1963. The last six months were as follows: July 1 MCF, August 0, September 0 MCF, October 2 MCF, November 0, December 7 MCF. The well was first treated at completion, and additional treatment does not appear to be beneficial.

It is proposed to spot 15 sack cement plug 2190'-2230' (covering parts 2124'-2190'), 13 sack plug from 1460-1500' (base of the Alamo 1950'), and 10' cement plug in top of casing with regulation 1" material, clean and abandon location. (5-1/2" OD casing is not to be pulled.)



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Supervisor

DATE

February 3, 1966

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: