

(SUBMIT IN TRIPLICATE)

Indian Agency **Navajo**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee **062591**
Lease No. **14 20 603 1266**

1	2	3	4	5	6	7	8	9	10

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	☒	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

NOV 19 1960, 19

Well No. **1-27** is located **660** ft. from **N** line and **2060** ft. from **W** line of sec. **27**
27 **25N** **11W** **10PM**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blind **San Juan** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is **6504** ft. (**6571'** Ground Level)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The estimated TD is 5300', and production from the Gallup Formation at about 5200'. We plan to drill to TD using air for circulation drilling through the Gallup Formation, cementing and fracturing through perforations. We plan to set 60' of 32.75 1 1/4" conduit casing set with one yard of cement. Then set 1000' of 1 7/8 7" surface casing set in an 8 5/8" hole with 150 sacks of cement, and last set a production string at about 5300' of 9 1/2 4 1/2" (or 14 5/8") casing in a 6 1/2" hole cemented with 100 sacks of cement.

We plan to core 50' of the Gallup Formation.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **H.F. Sears**
 Address **424 Petroleum Bldg.**
Amarillo, Texas

By **Joe C. Stealy**
 Title **Office Manager**

10-10-1980

10-10-1980

UNITED STATES
DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D.C. 20535

REPORT OF INVESTIGATION

TO : DIRECTOR, FBI (100-441100)
FROM : SAC, NEW YORK (100-100000)
SUBJECT: [Illegible]
RE: [Illegible]

NY 100-100000

On 10/10/80, [Illegible] advised that [Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

