



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R360.4.
Approval expires 12-31-60.

Indian Agency Navajo

Allettee 062591

Lease No. 14 20 603 1286

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	<input type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	<input type="checkbox"/>
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	<input type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	<input type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL.....		<input type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

January 30, 1961

, 1961

Well No. 1-27 is located 660 ft. from N line and 2060 ft. from E line of sec. 27

<u>NW 27</u>	<u>25N</u>	<u>11W</u>	<u>NNPM</u>
(1/4 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)
<u>Bisti</u>	<u>San Juan</u>	<u>New Mexico</u>	
(Field)	(County or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is 6584 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud date, November 30, 1960

Set 204' of 8 5/8" 24# 8R Used casing and circulated with cement.

5145' of 4 1/2" (305' of 11.6# & 4840' of 9.5#) J-55 Youngstown R-2 8R production string. Cemented with 114 sacks cement and 2 sacks of gel.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company H.F. Sears

Address 424 Petroleum Building
Amarillo, Texas

By Joe C. Stealy
Title Office Manager



