

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. NAME OF OPERATOR Shell Oil Company	2. NAME OF OPERATOR GAS ☐ OIL ☐ WELL ☐ OTHER ☐
3. ADDRESS OF OPERATOR 1850 Lincoln Street, Denver, Colorado 80203	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) 1980' EST and 760' EST Section 22-25N-11W
5. PERMIT NO. 6450' OR 6450' DE	6. IF INDIAN, ALLOTTEE OR TRIBE NAME San Juan
7. UNIT AGREEMENT NAME East Mesa Unit	8. FARM OR LEASE NAME East Mesa Unit
9. WELL NO. 19	10. FIELD AND POOL, OR WILDCAT Dist. Town City
11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA Sec. 22-25N-11W	12. COUNTY OR PARISH San Juan
13. STATE New Mexico	14. ELEVATIONS (Show whether DF, RT, CR, etc.) 6450' OR 6450' DE

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON
CHANGE PLANS


WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

SUBSEQUENT REPORT OF:

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

All depths shown are from ground level.
7-24-71 - III & IV Latex Well Service Unit. Pulled rods.
Spotted cement plug from 4935' to 4865'. Pulled 2" tubing.
Worked 5-1/2" casing to true sand. Rigged up blue jet, shot 5-1/2" casing off at 1035'. Spotted cement plug from 1035' to 1175'.
50' inside casing and 160' above casing stop. Pulled up the hole.
Spotted cement plug from 475' to 375'. Pulled a total of 42 joints 1040' of 5-1/2" cas.
Spotted 10' cement plug in surface casing. Installed dry hole marker.
Completed B & A 7-21-71.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Lead Clerk

DATE

10-10-71

(This space for Federal or State office use)
APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side