Form 9-881 a (Feb. 1951)

Ä	 	
	 ٠	

(SUBMIT IN TRIPLICATE)

Ap	Prova	expir	es :2-31	-60.	
Land Office	- S	124	ે છ ,	_ev.	lasice
Lease No	37	778	3064		
Unit	ියා	730 1	3		

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

NOTICE OF INTE	NTION TO DRILL		SUBSEQUENT	REPORT OF WATER SHUT-O)FF
NOTICE OF INTE	NTION TO CHANGE PLAN	ıs	SUBSEQUENT	REPORT OF SHOOTING OR	ACIDIZING
NOTICE OF INTE	NTION TO TEST WATER	SHUT-OFF	1 11	REPORT OF ALTERING CASI	
NOTICE OF INTE	NTION TO RE-DRILL OR	REPAIR WELL	SUBSEQUENT	REPORT OF RE-DRILLING O	R REPAIR
NOTICE OF INTE	NTION TO SHOOT OR AC	IDIZE	1 11	REPORT OF ABANDONMENT	
	NTION TO PULL OR ALTI		SUPPLEMENTA	ARY WELL HISTORY	
NOTICE OF INTE	NTION TO ABANDON WEI	L			M.
	(INDICATE A	ABOVE BY CHECK MAI	RK NATURE OF REPORT	, NOTICE, OR OTHER DATA)	
			;	October 14	
Carse	on Unit		***************************************		, I
		1080 a c.	m N line and	660 ft. from \(\bar{\mathbb{E}}	line of see 24
Well 140	is iocated	IMARALIT. HO	III. 3 IIIIe and	W (W	Inte of sec.
∜F 24		25N	12/	经 技术	
	J Sec. No.)	(Twp.)	(Range)	(Meridian)	
Bieti		ian Jusn	y or Subdivision)	Sev Pe	EX 160 r Territory)
(Fie	eld)	(Count)	y or Subdivision)	(State o	r Terntory)
(State names of and	d expected depths to obj	ective sands; show a ing points, and all	izes, weights, and leng l other important prop	ths of proposed casings; in cosed work)	dicate mudding jobs, o
(State names of and	d expected depths to obj		izes, weights, and leng l other important prop d 1/3–10–57	yths of proposed casings; in posed work)	dicate mudding jobs, o
, 11-57 Far tre	n and cemented	Spadde 8 5/3* 24% Tanged up	d 10-10-57 , J-65 c ssing and wai ted o	g at 141' with] on coment. Test	100 sacks
, 11-57 Far tre	n and comented anted coment.	Spadde 8 5/3* 24% Tanged up	d 10-10-57 , J-65 c ssing and wai ted o	e at 141' with 1 on coment. Test	100 sacks
, 11-57 Fan tre and	n and comented ented coment. I casing with	Spuide 8 5/8* %4* **Inged up 700 ps1. **	d 10-10-57 , J-65 casing and waited c ifteen minute	e at 141' with 1 on coment. Test	RELEVED
, 11-57 Far tre	n and comented ented coment. I casing with	Specide 8 5/8* %4 Thenged up 700 ps1.	d 10-10-57 , J-65 casing and waited c ifteen minute	e at 141' sith 1 on coment. Test on Ca.	RELEVED
I understand the	n and comented ented coment. I casing with	Specide 8 5/3* 24 12 mged up 700 ps1. 7	d 10-10-57 , J-65 casing and waited cifteen minute	on coment. Test	ALLEN COM
I understand the Company Address 10	n and comented ented coment. I casing with nat this plan of work mu	Spudde 8 5/8* 24% Thenged up 700 ps1. 5	d 10-10-57 , J-65 casing and waited cifteen minute	e at 141' sith 1 on coment. Test on Ca.	L CON. COM
I understand the Company Address 10	n and comented anted coment. I casing with nat this plan of work mu- nat this plan of work mu- nat this plan of work mu- nat this plan of work mu-	Spudde 8 5/8* 24% Thenged up 700 ps1. 5	d 10-10-57 , J-65 casing and waited cifteen minute n writing by the Geole	on coment. Test	RELEVAN