

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Water Injection Well		5. LEASE DESIGNATION AND SERIAL NO. Navajo 14-20-603-1440	
2. NAME OF OPERATOR Shell Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Tribal Lands	
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80290		7. UNIT AGREEMENT NAME Carson Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 661.4' FEL Section 20		8. FARM OR LEASE NAME Unit	
14. PERMIT NO.		9. WELL NO. 41-20	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6447 KB		10. FIELD AND POOL, OR WILDCAT Bisti	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 20-T25N-R11W	
		12. COUNTY OR PARISH San Juan	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION
CLEANED AND READY FOR INSPECTION

18. I hereby certify that the foregoing is true and correct

SIGNED <u>L. P. Plauty</u>	TITLE <u>Div. Ops. Engr.</u>	DATE <u>SEP 27 1977</u>
(This space for Federal or State office use)		

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:
cc: NMO&GCC

PLUG & ABANDON

SHELL OIL COMPANY

FROM: 7/18-19/77

LEASE

CARSON UNIT

DIVISION

WESTERN

COUNTY

SAN JUAN

WELL NO.

ELEV

STATE

BISTI

41-20 WI

6447 KB

NEW MEXICO

NEW MEXICOBISTI FIELDCarson Unit 41-20
(P&A)

"FR" TD 5040. PB 5010. AFE #528966 provides funds to plug & abandon well. RU Bedford 7/15. Pulled & LD 153 jts tbg & pkr. 7/16 PU tbg workstring & ran to PBTD. Loaded hole w/mud. Spt'd 20 sx cmt plug over & above perfs. Pulled & LD tbg string. RU hyd jacks.

JUL 18 1977

Carson Unit 41-20
(P&A)

TD 5040. PB 5010. 7/18 Shot off csg @ 2050 & spt'd 35 sx cmt plug @ stub. Pulled csg to 1360 & spt'd 50 sx cmt plug @ Fruitland Coal. Pulled csg to 510 & spt'd 25 sx cmt plug @ Ojo Alamo. Pulled csg to 253 & spt'd 25 sx cmt across shoe of sfc csg. Fin'd pull'g csg & spt'd 10 sx cmt @ sfc. RD Bedford & installed abandonment marker.

FINAL REPORT

JUL 19 1977