
HNITED STATES

SUBMIT IN TRIPLICATE*

Form approved.

DEPARTM				5. LEASE DESIGNATION AND SERIAL NO. Mims No. 1 SF 078067 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTION OF THE PROPERTY	CES AND REPORTS (ls to drill or to deepen or plug b PION FOR PERMIT—" for such p	ON WELLS back to a different reservoir. roposals.)	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME	
OIL GAS WELL WELL OTHER 2. NAME OF OPERATOR			7. UNIT AGREEMENT NAME Carson Unit 8. FARM OR LEASE NAME		
Shell Oil Company 3. ADDRESS OF OPERATOR 1700 Broadway, Denver, 4. LOCATION OF WELL (Report location cle See also space 17 below.) At surface 660' FSL & 660' FEL Sec		State requirements.*	9. WELL NO. 44-14 10. FIELD AND POOL, OR BISTI 11. SEC., T., R., M., OR B SURVEY OR AREA		
NMPM, San Juan County, N.M. 14. FERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6421' KB			Section 14-T25N-R12W 12. COUNTY OR PARISH 13. STATE New Mexico		
16. Check App	propriate Box To Indicate N	Nature of Notice, Report, or C			
FRACTURE TREAT SHOOT OR ACIDIZE A	CLL OR ALTER CASING CLTIPLE COMPLETE BANDON* HANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report results Completion or Recompl	ABANDONMEN of multiple completion etion Report and Log for	ASING X	
	RATIONS (Clearly state all pertiner nally drilled, give subsurface loca		including estimated data	e of starting any	

WILL SEND FINAL SUNDRY WHEN LOCATION CLEANED AND READY FOR INSPECTION



cc: NMO&GCC

WELL P&A		
SHELL OIL COMPANY	LEASE CARSON INIT	BISTI
	TIMOON CIVII	WELL NO. 44-14
FROM: 10/19/77	THO PETE	ELEV 6421 KB
	COUNTY SAN JUAN	STATE NEW MEXICO

NEW MEXICO
BISTI FIELD
Carson Unit 44-14
(P&A)

"FR" TD 5001. AFE #571156 provides funds to plug & abandon well. 10/11 RU Bedford & pulled rods. Lowered tbg to PBTD & circ'd hole w/gel. Spt'd 25 sx cmt plug across & over Gallup perfs. Pulled tbg out of well. 10/13 Set jacks; csg stuck. Perf'd csg @ 1200' & spt'd 50 sx cmt plug & sqz'd 20 sx over Pictured Cliffs & Fruitland Coal. Perf'd csg @ 360' & placed 35 sx cmt & sqz'd 20 sx over Ojo Alamo Sd. Backed csg off @ 210'. Pulled to 175'. Placed 25 sx cmt plug over sfc csg stub. Pulled csg out of well. Placed 10 sx cmt plug on sfc. Set abandonment marker & RD Bedford.

FINAL REPORT