

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir,
Use "APPLICATION FOR PERMIT--" for such proposals.

SUBMIT IN TRIPLICATE

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
NM 070322

6. If Indian, Allottee or Tribe Name

7. If Unit or CA. Agreement Designation

Carson Unit

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

8. Well Name and No.
Carson Unit #33-15

2. Name of Operator
Giant Exploration & Production Company

9. API Well No.
33-045-05374

3. Address and Telephone No.
P.O. Box 2810, Farmington, New Mexico 87499 (505)326-3325

10. Field and Pool, or Exploratory Area
Bisti Lower Gallup

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980' FSL, 1980' FEL, Sec. 15, T25N, R12W

11. County or Parish, State
San Juan, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other Return to Production

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Giant Exploration & Production Company intends to return the subject well to production as follows:

- 1) Clean out to a PBD of 4860'.
- 2) Pressure test casing.
- 3) Acidize existing perforations (4696'-4714', 4726'-4768', 4778'-4788', 4796'-4804') with 1000 gal. 15% HCl.
- 4) Install production tubing string. (Note: if casing leaks are encountered, a 3-1/2" liner with isolating packers will be run across the leaking interval prior to running the production string.)
- 5) Install pumping unit.
- 6) Return well to production.

RECEIVED
AUG 24 1995

SEE 300.1 DEVL
DIST. 2

14. I hereby certify that the foregoing is true and correct

Signed Paul R. Williams
Paul R. Williams

Title Area Engineer

Date AUG 08 1995

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____ Date _____

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any manner within its jurisdiction.

*See Instruction on Reverse Side

APPROVED

AUG 11 1995
/s/ Ken Townsend
DISTRICT MANAGER