Form 9-331 (May 1963)					ICATE*	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. L. M. Phillips No. 7 NM 070322 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
(Do not use	SUNDRY NO this form for prop Use "APPLIC	TICES AND REP	ORTS O	N WELLS ck to a different reservoir posals.)	r.		
1. OIL G	AS OTHER		Carson Unit 8. FARM OR LEASE NAME				
Shell Oil 3. ADDRESS OF OPE	ERATOR		Unit 9. WELL NO.				
1700 Broadway, Denver, Colorado 80290 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1989' FSL & 1984' FEL Section 15						23-15 10. FIELD AND POOL, OR WILDCAT Bisti 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA Section 15-T25N-R12W	
14. PERMIT NO.		15. ELEVATIONS (Show		RT, GR, etc.)		12. COUNTY OR PAR. San Juan	New Mexico
TEST WATER S FRACTURE TRE SHOOT OR ACH REPAIR WELL (Other) 17. DESCRIBE PROPE proposed we nent to this s	NOTICE OF INT	heck Appropriate Box To Indicate N OF INTENTION TO: PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS PLETED OPERATIONS Clearly state all pertinent is directionally drilled, give subsurface locat		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report result Completion or Recond		REPAIRING WELL ALTERING CASING ABANDONMENT* As of multiple completion on Well pletion Report and Log form.)	
		See a	attachme	ent			
	FINAL SUNDE	RY WHEN LOCATION	N				
						A second	

cc: New Mexico O&GCC w/attachment

PLUG AND ABANDON WELL			BISTI		
SHELL OIL COMPANY	LEASE	CARSON UNIT	WELL NO.	23-15	
	DIVISION	WESTERN	ELEV	6234 GR	
FROM: 6/3/77	COUNTY	SAN JUAN	STATE	NEW MEXICO	

NEW MEXICO
BISTI FIELD
Carson Unit 23-15
(P&A)

"FR" TD 4917. PB 4732. AFE #520596 provides funds to plug and abandon well. 5/27 RU Bedford Inc. Tag'd top of pkr @ 4622. Loaded hole w/mud. Spt'd 20 sx cmt w/1# per sx flocele on top of pkr. Pulled & LD tbg. 5/28 RU hyd jacks. Shot off csg @ 1031 & spt'd 50 sx cmt plug @ csg stub. Pulled csg to 390' & spt'd 50 sx cmt plug across base of 8-5/8 csg. Fin'd pull'g csg. Spt'd 10 sx cmt plug @ sfc & installed abandonment marker. RD Bedford Inc. FINAL REPORT