Form	9-331
(May	1963)

REPAIR WELL

(Other)

UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

SUBMIT IN TRIPLICATE.

Budget Bureau No. /42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

CEOL	OCICAL	CHEVEV
GEOL	OGICAL	SURVEY

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

CHANGE PLANS

NM (በ ጊ /	ເລ	57
TAKE.	יעט	2	در

	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	

OIL GAS WELL OTHER 2. NAME OF OPERATOR			7. UNIT AGREEMENT NA	East Bisti Unit 8. FARM OR LEASE NAME		
			East Bisti Un			
			8. FARM OR LEASE NAM			
Skelly Oil Company						
3. ADDRESS OF OPERATOR			9. WELL NO.			
1860 Lincoln Street, Den	ver, Colorado 80203		2			
4. LOCATION OF WELL (Report location cle	early and in accordance with any	State requirements.*	10. FIELD AND POOL, OF	R WILDCAT		
See also space 17 below.) At surface			Bisti Lower C	Gallup		
1976' FSL & 659' FWL	Section 16-25N-11W		11. SEC., T., R., M., OR B SURVEY OR ABEA Section 16-25	5N-11W		
14. PERMIT NO.	15. ELEVATIONS (Show whether DF.	RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE		
•	6415' GR	6423.6' KB	San Juan	New Mexico		
16. Check Ap	propriate Box To Indicate N		r Other Data			
TEST WATER SHUT-OFF	ULL OR ALTER CASING	WATER SHUT-OFF	BEPAIRING V	WELL		
FRACTURE TREAT	ULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	·		
SHOOT OF ACIDIZE	BANDON*	SHOOTING OR ACIDIZING	ABANDONME	NT* XX		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

All depths shown are from ground level. 7-29-71 - MI & RU Aztec Well Service Unit. Pulled rods. Spotted cement plug from 4951' to 4851'. Pulled 2" tubing Worked 4-1/2" casing to free same. Rigged up Blue Jew, shot casing off at 1626'. Spotted cement plug from 1676' to 1576', 50' inside casing stub and 50' above 4-1/2" casing stub. Pulled casing up the hole. Spotted cement plug from 1315' to 1165'. Pulled up the hole. Spotted cement plug from 460' to 360' Pulled total of 38 joints 1630' of 4-1/2" casing. Spotted 10' cement plug in surface casing. Installed dry hole marker.

Completed P&A 8-10-71.

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

18. I hereby certify that the foregoing is true and correct SIGNED (This space for Federal or State office use) DATE TITLE APPROVED BY . CONDITIONS OF APPROVAL, IF ANY:

*See Anstructions on Reverse Side