DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side) Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO. Form 9-331 (May 1963) L. M. Phillips No. GEOLOGICAL SURVEY SF 078063 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT..." for such proposals.) 1 7. UNIT AGREEMENT NAME Water Injection Well OTHER Carson Unit 2. NAME OF OPERATOR 8. FARM OR LEASE NAME Shell Oil Company Unit 3. ADDRESS OF OPERATOR 9. WELL NO. 1700 Broadway, Denver, CO 80290 24-7 LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface 10. FIELD AND POOL, OR WILDCAT Bisti 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 660' FSL & 1971' FWL Section 7 Section 7-T25N-R11W 12. COUNTY OR PARISH 13. STATE 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6356.76 KB San Juan N.M. 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF; REPAIRING WELL WATER SHUT-OFF TEST WATER SHUT-OFF PULL OR ALTER CASING FRACTURE TREATMENT ALTERING CASING FRACTURE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDON MENT REPAIR WELL CHANGE PLANS (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) * See attachment APPROVED WILL SEND FINAL SUNDRY WHEN LOCATION CLEANED AND READY FOR INSPECTION JUN 2 9 1978 A MCGRATH

DESTRUCT ENGINEER 18. I hereby certif is true and correct SEP 2 6 1977 Div. Opers. Engr. TITLE (This space for Federal or State office use) APPROVED BY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

NMO&GCC

NEW MEXICO O'L CONSERVATION COMM.

1000 PIO BRAZOS RO. AZTEC, NEW MEXICO 87410

*See Instructions on Reverse Side

SEP 30 1977

NEW MEXICO | BISTI FIELD Carson Unit 24-7 WI (P&A)

"FR" TD 5040. PB 4932. AFE #529576 provides funds to plug & abandon well. 7/27 RU Bedford. Pulled & LD 152 jts 2-3/8 tbg & pkr. 7/28 PU 2-3/8 tbg workstring & ran to PBTD. Circ'd hole w/mud. Spt'd 20 sx cmt plug across & above perfs. Pulled & LD workstring. RU hyd jacks JUL 2 9 19

Carson Unit 24-7 WI (P&A)

TD 5040. PB 4932. 7/29 Shot off csg @ 1985 & spt'd 35 sx cmt plug over csg stub. Pulled csg to 1335 & spt'd 50 sx cmt plug across Fruitland Coal. Pulled csg to 420 & spt'd 35 sx cmt plug across Ojo Alamo. Pulled csg to 175 & spt'd 25 sx cmt plug across stub of 8-5/8 csg. Spt'd 10 sx cmt plug @ sfc. 7/30 Installed abandonment marker. RD Bedford FINAL REPORT