



DIRECTOR
JOE D. RAMEY

OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS RD. - AZTEC

87410
LAND COMMISSIONER
PHIL R. LUCERO



STATE GEOLOGIST
EMERY C. ARNOLD

March 20, 1978

Mr. Roger Plenty
Shell Oil Company
1700 Broadway
Denver, Colorado 80202

Re: Carson Unit #44-10
P-10-25N-12W
Bisti Lower Gallup Pool

Dear Mr. Plenty:

The attached remedial prognosis for the subject well will be suitable for temporary repair.

Cement will be required between the Mesaverde and Gallup formations at the time the well is plugged and abandoned.

The expense of plugging may be greatly increased if the casing does collapse in the meantime.

If there are questions, please contact us.

Yours very truly,

A. R. Kendrick
Supervisor, District #3

xc: U.S.G.S., Farmington

ARK:no