'Form 9-331 (May 1963)
---------------------------

## UNITED STATES SUBMIT IN TRIPLICATE\* Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND BERIAL NO.

SF 078056

	GEOL	OGICAL	SURVEY		
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS

	ALLOTTEE		

(Do not use this form for proposals to drill or to deepen or plug back to a different res Use "APPLICATION FOR PERMIT" for such proposals.)	ervoir.
OIL GAS OTHER Injection	7. UNIT AGREEMENT NAME Central Bisti Unit
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
Hixon Development Company	
3. ADDRESS OF OPERATOR	9. WELL NO.
P. O. Box 2810, Farmington, New Mexico 87401	GI-14
<ol> <li>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.         See also space 17 below.)         At surface     </li> </ol>	10. FIELD AND POOL, OR WILDCAT Bisti Lower Gallup
1980' FNL, 1980' FEL, Section 8, T25N, R12W	Section 8, T25N, R1
14. PERMIT NO.   15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
6189' GLE	San Juan NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

TEST WATER SHUT-OFF  PULL OR ALTER CASING  WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE  PULL OR ALTER CASING  MULTIPLE COMPLETE  SHOOTING OR ACIDIZING  WATER SHUT-OFF  REPAIRING WELL  ALTERING CASING  SHOOTING OR ACIDIZING	NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
(Other)  CHANGE PLANS  A  (Other)  (Other)  Completion or Recompletion Report and Log form.)	FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  MULTIPLE COMPLETE  ABANDON*  CHANGE PLANS  X	FRACTURE TREATMENT SHOOTING OR ACIDIZING ABANDONMENT*		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) •

It has been determined that the above captioned well will be required to meet Central Bisti Unit Water Injection requirements. It is proposed to retain this well as a water injection well by repairing injection packer and cleaning out the perfs with 1500 gallons 15% HCl acid.



8. I hereby certify that the foregoing is true and correct		Petroleum Engineer	December 3, 1981
(This space for Federal or State office use) (Orig. Sid.) RAYLOND W. VISTARD APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE _	RAYMOND W. VINYARD ACTING DISTRICT SUPERVISOR	DEC 0 8 1981