Form 9-331 (May 1963)	UNITED STATES DEPARTMENT OF THE IN	ΕΥ		Form approve Budget Bures 5. LEASE DESIGNATION SI 078056 6. IF INDIAN, ALLOTTEE	tu No. 42-R1424. AND SERIAL NO.
	SUNDRY NOTICES AND REPORE this form for proposals to drill or to deepen of Use "APPLICATION FOR PERMIT—" for				
1. OIL -57 G	AS 🗀			7. UNIT AGREEMENT NA	
	ELL OTHER	Central Bisti Unit			
2. NAME OF OPERA	TOR	8. FARM OR LEASE NAME			
Hixo	on Development Company	Central Bisti Unit			
3. ADDRESS OF OPE	ERATOR	9. WELL NO.			
Р.О	. Box 2810, Farmington, Ne	64			
	LL (Report location clearly and in accordance wi	10. FIELD AND POOL, OR WILDCAT			
See also space 17 below.) At surface				Lower Gallup	
1980	'FNL, 1980' FEL, Section	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA			
				Section 7, T	25N, R12
14. PERMIT NO.	15, ELEVATIONS (Show who	ether DF, RT, (	R, etc.)	12. COUNTY OR PARISH	13. STATE
	6274' C	LE		San Juan	NM

(Other) CHANGE PLANS REPAIR WELL (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Return well to pump (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

It is planned to return this TA Lower Gallup oil well to pump.


NOTICE OF INTENTION TO:

 $\mathbf{x}$ 

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*



SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

18. I hereby certify that the foregoing is true and cor	root				
		roleum Engineer	DATE 5-7-80		
(This space for Federal or State office use)			ASSEPTED FOR RECORD		
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE		MAY 30 1980		
ch 3ml	*0 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	10 Paires Cida	ere consumate DISTRICT		

16.

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

proposed work. I nent to this work.)

See Instructions on Reverse Side

R12W