Form 3160-5 (June 1990)

Anenber

UNITED STATES Exp 5 Lease

BUREAU OF LAND MANAGEMENT FEB 200

FORM APP	ROV	ED
get Rureau No.	1004	012

Expires: March 31, 1993

5. Lease Designation and Serial No. SF 078056

6. If Indian, Allottee or Tribe Name

SUNDRY NOTIC	ES AND REPORTS	ON WELLS	o. If fidial, Affolice of Tribe Name	
Do not use this form for proposals	s to drill or to deepen or re-	atry to a different reservoir,	7. If Unit or CA. Agreement Designation	
Use "APPLICATIO	ON FOR PERMIT" for s	uoti proposals	, and the second	
SUBM	IIT IN TRIPLICATE		Central Bisti Unit	
1. Type of Well			8. Well Name and No.	
	as Well X Other	Water Injection Well	Central Bisti Unit-19	
2. Name of Operator			9. API Well No.	
Central Resources, Inc. for Giant Exploration & Production Company			30-045-055014	
3. Address and Telephone No.			10. Field and Pool, or Exploratory Area	
P.O. Box 1213, Bloomfield, New Mexico 87413 (505)632-3476			Bisti Lower Gallup	
4. Location of Well (Footage, Sec., T.,	R., M., or Survey Descrip	tion)	11. County or Parish, State	
660' FNL, 660' FEL, Sec. 7			San Juan, New Mexico	
12. CHECK APPROPRIATE BOX	(s) TO INDICATE NAT	URE OF NOTICE, REPORT	, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION	ON	
	X Aban	donment	Change of Plans	
Notice of Intent	Recor	mpletion [New Construction	
	Plugg	ing Back	Non-Routine Fracturing	
Subsequent Report	Casin	g Repair	Water Shut-Off	
	Alteri	ng Casing	Conversion to Injection	
X Final Abandonment Notice	Other	Ī	Dispose Water	
			Note: Report results of multiple completion on Well	
		C	ompletion or Recompletion Report and Log form.)	
13. Describe Proposed or Completed Oper	ations (Clearly state all pert	nent dates, including estimated da	te of starting any proposed work. If well is	
directionally drilled, give subsurface lo	ocations and measured and to	rue vertical depths for all markers	and zones pertinent to this work.)*	
January 2-5th.				
A. Set a CIBP at 4758' and	spot cement on top to	o 4658' using 30 sacks cen	nent.DIDN'T HOLD	
B. Bring top of Gallup plug from 4588' to 4420' inside outside 5 1/2" casing using 30 sacks cement.				
C. Set Mesa Verde plug from 1962' to 1862' inside and outside 5 1/2" casing using 47 sacks cement.				
h.mg .		and oddido 5 1/2 od.	mb asing 1/ sacks coment.	

E. Set the Fruitland Coal plug from 910' to 810' inside and outside 5 1/2" casing using 47 sacks cement.

D. Set the Pictured Cliffs Plug from 1230' to 1130' inside and outside 5 1/2" casing using 47 sacks cement.

F. Place the surface plug at 242' to surface inside and outside the 5 1/2" casing using 95 sacks cement

H. Cut well head and install dry hole marker. Clear and remediate location.

14. I hereby certify that the foregoing is true and Signed	correct Title Production Technician	Date	01/15/2001
Patty Shelton	The Floudetion Technician	Date	01/15/2001
(This space for Federal or State office use) Approved by	Title	Date	÷ :
Conditions of approval, if any:		_	CCEPTED FOR RECORL

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false fictitious or fraudulent statements or representations as to any manner within its jurisdiction.