Form 9-331 (May 1963)

16.

UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

L. M. Phillips No. 7 NM 070322 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

GEOLOGICAL SURVEY

Use "APPLICATION FOR PERMIT—" for such proposals.)			
OIL GAS WELL OTHER Water Injection Well	7. UNIT AGREEMENT NAME Carson Unit		
2. NAME OF OPERATOR	8. FARM OR LEASE NAME		
Shell Oil Company	Unit		
3. ADDRESS OF OPERATOR	9. WELL NO.		
1700 Broadway, Denver, Colorado 80290	31-10		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT Bisti		
660' FNL & 1980' FEL Section 10	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA Section 10-T25N-R12W		
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE		
6240' DF	San Juan N.M.		

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results of my Completion or Recompletion	REPAIRING WELL ALTERING CASING ABANDONMENT®
131			. Completion of Recompletion	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION CLEANED AND READY FOR INSPECTION



SIGNED TITLE Div. Opers.	Engr. SEP 2 7 1977
APPROVED BY	DATE
cc: NMO&GCC FOR TAMES F SIMS NMOCC	SER SQ 577
DISTRICT ENGINEER See Instructions on Reverse Signature	•

PLUG & ABANDON

SHELL OIL COMPANY	LEASE CARSON UNIT		BISTI
FROM: 9/19-22/77	DIVISION WESTERN	WELL NO	31-10 6240 DF
	COUNTY SAN JUAN	STATE	NEW MEXICO

NEW MEXICO BISTI FIELD;

Carson Unit 31-10

(P&A)

SEP 1 9 1977

"FR" TD 4995. PB 4933. AFE #529586 provides funds to plug & abandon well. 9/15 RU Bedford. Pulled on tbg; pkr stuck. 9/16 Worked on stuck pkr; could not get loose. Spt'd 20 sx cmt plug thru tbg in hole over & across Gallup perfs. Turned tbg to the right. Backed pkr off @ safety jt. Pulled tbg out of hole.

Carson Unit 31-10 (P&A)

TD 4995. PB 4933. No report.

SEP 2 0 1977

Carson Unit 31-10 (P&A)

TD 4995. PB 4933. No report.

SEP 2 1 1977

Carson Unit 31-10 (P&A)

TD 4995. PB 4933. 9/17 Set jacks & worked csg. 9/19 Shot csg @ 1228 & spt'd 50 sx cmt plug over csg stub - Pictured Cliffs & Fruitland Coal. Pulled csg to 307 & spt'd 25 sx cmt plug over Ojo Alamo Sd & sfc csg stub. Pulled rest of csg out of hole. Placed 10 sx cmt plug on sfc. Set abandonment marker & RD Bedford. SEP 2 2 1977