

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078155
Unit Gov't Marye

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Set Surfacing Casing</u>	<u>XX</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 4, 1958

Well No. 8 is located 660 ft. from XXXX line and 1980 ft. from E line of sec. 1


G SW SE Section 1 25N 13W New Mexico PM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Bisti-Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of ~~the derrick floor~~ above sea level is 6239 ft. GL

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 13-3/4" hole to 211' KB. Ran 5 joints 9-5/8 Armo Spiral Weld Casing. Landed @ 210' KB and cemented w/175 sac regular cement. Displaced cement to 190' KB w/good returns to surface. Waited 24 hours, then tested. Casing held okay.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The British-American Oil Producing Company
Address Box 180
Denver 1
Colorado
By Thomas M. Hagan
Title District Superintendent