

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

December 26, 1985

Mr. Al Kuchera Hixon Development Co. 501 Airport Dr. Farmington, NM 87401

Re: Central Bisti Unit #56 M-5-25N-12W

Dear Mr. Kuchera:

The annual mechanical integrity test on the referenced water injection well indicated a casing or packer leak. In order to insure the protection of hydrocarbon and fresh water zones, you are hereby directed to initiate remedial action within 30 days.

Yours truly,

Carolyn J. Yaplin Field Representative

xc: Prentiss Childs

/Well File UIC File

Operator File