


Form 9-331a
(Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078155
Unit Gov't Marye

RECEIVED

OCT 10 1958

SUNDRY NOTICES AND REPORTS ON WELLS

U.S. GEOLOGICAL SURVEY
SANTA FE, NEW MEXICO

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	
To Sandfrase	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 10, 1958

Well No. 3 is located 660 ft. from N line and 1980 ft. from W line of sec. 1

C NE NW Section 1
(1/4 Sec. and Sec. No.)

25N
(Twp.)

13W
(Range)

New Mexico PM
(Meridian)

Bisti-Gallup
(Field)

San Juan
(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the ~~derrick floor~~ above sea level is 6211 ft. 01

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is proposed to clean out to 4948' KB. Set bridge plug at 4892' KB. Sandfrase w/30,000# sand in 30,000 gallons of lease crude using 15 gal Dowell J-90 per 1,000 gal frase fluid. Swab casing, drill out bridge plug, and clean out to PBD. Run tubing, pump, and rods and place well on production.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The British-American Oil Producing Company

Address Box 190

Denver 1

Colorado

Original Signed By:
By Thomas M. Hogan

Title District Superintendent