

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Water Injection Well</u>	7. UNIT AGREEMENT NAME <u>Central Bisti Unit</u>
2. NAME OF OPERATOR <u>Hixon Development Co.</u>	8. FARM OR LEASE NAME <u>CBU</u>
3. ADDRESS OF OPERATOR <u>341 Milam Bldg. SAN Antonio, Texas</u>	9. WELL NO. <u>WI 5</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>1319 fsl $\frac{1}{2}$ 1315 fsw Sec 10, T25N R12W</u> <u>SAN JUAN Co. New Mexico</u>	10. FIELD AND POOL, OR WILDCAT <u>Bisti Gallup</u>
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec 10, T25N R12W</u> <u>40 pm</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>6212 DF</u>	12. COUNTY OR PARISH <u>SAN JUAN</u>
	13. STATE <u>N.M.</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well has been Abandoned as follows:

6/26/74 Squeezed Perfs 4742-4846 w/15sx
Spot 10sx Plug over Pt. Lookout inside Csg.

6/28/74 Cut 4 1/2" Csg off @ 1727', Pulled Same.
Spot 30sx Plug over Stub 1680-1780
Spot 40sx Plug over P.C.

6/29/74 Set P&A marker w/10sx Plug.



18. I hereby certify that the foregoing is true and correct

SIGNED Larry Bedford

TITLE Agent for Operator

DATE Sept 25, 74

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE
SEP 25 1974