

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM-6896

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Nageezi

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Dufers Point GL DK

11. SEC., T., R., M. OR S.E. AND SURVEY OR AREA

Sec. 12, T25N, R9W
NMPM

12. COUNTY OR PARISH 13. STATE

San Juan

NM

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR

Meridian Oil Inc.

3. ADDRESS OF OPERATOR

P.O. Box 4289 Farmington, New Mexico 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

1500'N, 1500'E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, ST, GR, etc.)

6431' GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

4-27-89 MOL RU. TOOH w/233 3/4" rds. nd tree. nu bop. Tih w/2+ jts tbg tag @ 5976'. TOOH w/127 2 3/8" tbg. Pu 3 7/8" drag bit & 4 1/2" csg scraper. TIH. RU power swivel. TOOH. tbg broke @ co. left 36 jts tbg, csg scraper & bit in hole. TIH w.overshot. tag fish. Overshot would not catch fish-slipped off. TOOH. RU os & TIH. Tag fish. TOOH. Ld os & pu 3 7/8" flat btm mill, 6-dc's. TIH. Tag fish. Nu rig pump, circ.. Mill. Milled off 3'. TOOH. LD mill. Pu os. Tih tag fish, os would not engage. TOOH ld so. PU 3 7/8" flat btm mill, 6-dc's. Tih w/2 3/8" ws. Tag fish. Nu Ps & rig pump. Circ. Mill. Milled off 5'. circ. POOH. LD 3 7/8" flat btm mill. Pu 8 x 3 3/4" wash pipe. Tag fish. Nu ps & rig pump. Wash down tbg 6'. LD wash pipe. Pu os, hydraulic jars, accelerator. TIH. Tag fish. Os engaged fish. Jarred tbg loose. Pull 8 stds of tbg. TOOH. Ld hydraulic jars & bumper sub, 6-dc's & os. Finish tooh w/34 jts 2 3/8" tbg, csg scraper & 3 7/8" drag bit. LD 185 jts old tbg. PU 3 7/8" mill. Tih. Tag bp. Nu ps & rig pump. Mill. Milled down 6011'. Tooh. Ld mill. PU bp. Tih set bp @ 6010'. TOOH. Ld seating tool. Tih 186 jts 2 3/8" tbg w/perf sub & sn. Nu tbg hanger, land tbg @ 5835', sn & perf sub 1 jt off btm @ 5799'. Nd bop. Nu tree. tih w/2 x 1 1/4 x 12 x 13 pump w/loc no plunger 230 3/4" rods 1-8', 1-4', 2-2' pony rods. space out. Hang off. Press test tbg to 500#.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Regulatory Affairs

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

ACCEPTED FOR RECORD

JUN 05 1989

FARMINGTON RESOURCE AREA

BY

*See Instructions on Reverse Side