

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-6597-2

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Hixon Development Company	8. Farm or Lease Name Mandana State Com.
3. Address of Operator P.O. Box 2810, Farmington, New Mexico 87401	9. Well No. 1
4. Location of Well UNIT LETTER <u>C</u> <u>790'</u> FEET FROM THE <u>north</u> LINE AND <u>1850</u> FEET FROM THE <u>west</u> LINE, SECTION <u>2</u> TOWNSHIP <u>25 north</u> RANGE <u>12 west</u> NMPM.	10. Field and Pool, or Wildcat WAW-Fruitland-PC
15. Elevation (Show whether DF, RT, GR, etc.) 6272' GLE	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rig up swab unit 8/26/80. Pull 1-1/4" tubing. Acidize well with 500 gallons 15% MSR acid. Displace with 10 barrels 2% KCl water. Swab well back. Re-run 1-1/4" tubing. Hang well back on pipeline 8/29/80.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>Frank I. Chavez</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>3/31/81</u>	
APPROVED BY <u>Original Signed by FRANK I. CHAVEZ</u>	TITLE <u>SUPERVISOR DISTRICT # 3</u>	DATE <u>APR 2 1981</u>	
CONDITIONS OF APPROVAL, IF ANY:			