

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR  
Coleman Oil & Gas, Inc.

3. ADDRESS OF OPERATOR  
P. O. Drawer 3337, Farmington, N. M. 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface  
2090' FSL & 1960' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
6500' KB

5. LEASE DESIGNATION AND SERIAL NO.  
N00-C-14-20-5249

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
Allottee Kosa Ken Noto

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Bisti

9. WELL NO.  
1

10. FIELD AND POOL, OR WILDCAT  
Bisti Lower Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 23, T25N, R11W NMPM

12. COUNTY OR PARISH  
San Juan

13. STATE  
N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

☐  
☐  
☐  
☒  
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☐  
☐

☐  
☐  
☐  
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Request permission to plug and abandon the subject well because the oil & gas lease has expired.

It is proposed to: (Work to be performed within 90 days of receiving approval of plugging program)

1. Set BP @ 4900' <sup>35</sup> ± & cap w/ <sup>15</sup> sks class B neat cement. (Cap w/ 35 sks) \* See Attached
2. Spot a 25 sk class B neat cement plug at 800'. This plug will isolate the Ojo Alamo from zones below. Inside & outside casing
3. Spot a 25 sk class B neat cement plug at 400'. This plug will be across the shoe of the surface casing. to surface inside & outside casing
4. Install dry hole marker.
5. Reclaim surface as required.

This plugging program will isolate all known water zones & oil-gas zones.

CORRECTED

JAN 05 1987

18. I hereby certify that the foregoing is true and correct

SIGNED

L. O. Van Ryan

TITLE President

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JAN 6 1987

OIL CON. DIV.

DIST. 3A  
DATE 12-30-86

AREA MANAGER

\*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT  
CALLER SERVICE 4104  
FARMINGTON, NEW MEXICO 87499

Attachement of Notice of  
Intention to Abandon

Re: Permanent Abandonment

Well: 1 Bisti

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
2. The Farmington Office, telephone (505) 325-4572, is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.

4. The following modifications to your plugging program are to be made (when applicable):

plug 2803-2703 Cliff House  
" 1750-1650 Chacra  
" 1318 1418 Pictured Cliffs  
" 1122-1022 Fruitland

move Ojo Alamo plug to 600-270' (Surface casing shoe & Ojo Alamo)  
inside & outside 4 1/2" casing

plug 0-50 surface plug inside & outside 4 1/2" casing

Office Hours: 7:45 A.M. to 4:30 P.M.