<u>New Mexi</u>co

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\* CHANGE PLANS

TEST WATER SHUT-OFF

PRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

Spudded well. Drilled surface hole. 10-31-74 Ran 3 joints 8 5/8", 24# K-55 surface casing, 116' set at 126'. Cemented with 112 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/ 30 minutes.

18.	I hereby certify that the foregoing is true and correct		
	I hereby certify that the foregoing is true and correct SIGNED L. G. Diww	TITLE Drilling Clerk	DATE November 4, 1974
	(This space for Federal or State office use)		Margar and the state of the sta
	APPROVED BY	TITLE	DATE