5. LEASE

## UNITED STATES

OF THE INTERIOR	Jicar <u>illa Contract #92</u>
DEPARTMENT OF THE INTERIOR	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SURVEY	Jicarilla Apahce
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME Jicarilla 92
1. oil gas well other	9. WELL NO. #11
2. NAME OF OPERATOR Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME Tapacito Pictured Cliffs
3. ADDRESS OF OPERATOR P.O. Box 90, Farmington, N.M. 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec 30, T27N, R3W
below.) AT SUBFACE: 1800 FNL & 1490 FEL SW/NE	12. COUNTY OR PARISH 13. STATE N.M.
AT TOP PROD. INTERVAL: 1800 FNL & 1490 FEL AT TOTAL DEPTH: 1800 FNL & 1490 FEL	14. API NO. 30-039-22919
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7275' KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING  REC E AUG2	
MULTIPLE COMPLETE  CHANGE ZONES  BUREAU OF LAND FARMINGTON RE	- MANIAGEMENT
location Clean up	·
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones perting.)	ate all pertinent details, and give pertinent dates directionally drilled, give subsurface locations and ent to this work.)*

Location clean up and reseeding completed on 8-19-83.

