UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

BUREAU OF LAND MANAGEMENT	
OUNDRY/NOTICES AND DEPORTS ON MELLS	Rincon Unit
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.	6. If Indian, Allotee or Tribe Name
Use "APPLICATION FOR PERMIT"-for such proposals	
SUBMIT IN TRIPLICATE	7. If Unit or CA. Agreement Designation
Type of Well	SF 080385
Oi X Gas Well Other	Well Name and No.
Well Well Other	RINCON UNIT 185E
Union Oil of California/dba UNOCAL	9. API Well No.
Address and Telephone No.	30-039-25439
P.O. BOX 850	10. Field and Pool, or Exploration Area
1550' FSL & 1505' FEL	Basin Dakota/Blanco Mesa Verd
Sec. 22, T27N, R07W	Rio Arriba
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	
TYPE OF SUBMISSION TYPE OF ACTION	
Notice of Intent Abandonment	Change of Plans
Recompletion	New Construction
X Subsequent Report Plugging Back	Non-routine Fracturing
	Water Shut-Off
Casing Repair	브
Final Abandonment Notice Altering Casing	Conversion to Injection
	Conversion to Injection Dispose Water (Note: Report results of multiple completion on We
Final Abandonment Notice Altering Casing Other Down Hole Commingling Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W
Final Abandonment Notice Altering Casing Other Down Hole Commingling Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a give subsurface locations and measured and true vertical depth for all markers and zones pertinent to this work.)* "SEE ATTACHED"	Conversion to Injection Dispose Water (Note: Report results of multiple completion on W

*See Instructions on Reverse Side

RINCON UNIT #185E

0:0

Type of Report

WORKOVER/DHC

Lease Well 511310-185E

State: NM

County:RIO ARRIBA

Activity Date 8/18/2000

Day #: 0

INITIAL REPORT

Times

Hours Remarks

MIRU KEY; ATTEMPT TO INSTALL BPV IN LONGSTRING HANGER; DID NOT HAVE CORRECT TOOL; PUMP 20 BFW DOWN DAKOTA STRING; ND TREE: INSTALL FLOAT IN LONG STRING: NU BOP & BLOOIE LINE; TOOH W/ SHORT STRING; STAND BACK 174 JTS. (5446.8'); LD SN & TAIL JT. (31.6'); DUMP 20 BFW DOWN ANNULUS; ATTEMPT TO UNSET PKR; NO SUCCESS; ND CROSS & BLOOIE LINE; PUMP 10 BFW DOWN TBG; REMOVED FLOAT; REMOVED HANGER; NU CROSS & BLOOIE LINE; WORK PKR 30 MIN. & UNSET; PUH 7 STANDS; PKR DRAGGING FIRST 4 CSG COLLARS & THEN

FREE: SDFN. SD DUE TO LIGHTNING STORM; 30 BLTR.

Activity Date 8/19/2000

Day # 2

Time

Hours Remarks

> BLOW WELL TO PIT. FINISH POH. LONGSTRING TOTAL 237 JTS (7442"). PU & TIH W/2-3/8" SAW TOOTH CLR, EXP CHECK VALVE. SN, ON 238 JTS 2-3/8" 4.7# J-55 USED TBG. PU JT AND CLEAN OUT TO 7510'. RECOVERED SAND, CEMENT, AND SCALE. PU AND LAY DOWN JT. ND CROSS AND BLOOIE LINE. ND BOP. LND TBG. DROP BALL AND NU TREE. RU AMERICAN ENERGY SERVICE. PUMP 1000 GALS 15% HCL + ADDITIVES. DISPLACED WITH 10 BBLS AND LET FALL. TBG ON VACUUM. RU AIR. CIRC HOLE CLEAN/2 HRS. TR 68 BBLS OF 70 LOAD. LEFT WELL FLOWING TO PIT. WILL RD MONDAY MORNING.

Activity Date8/22/2000

Day #3

FINAL REPORT

Times

Hours

Remarks

RDMO KEY WELL SERVICE.