

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to recomplete an abandoned well. Use Form 3160-3 (APD) for such proposals.

02 AUG 13 AM 10:43
BLM

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
ENERGEN RESOURCES CORPORATION

3a. Address
2198 Bloomfield Highway, Farmington, NM 87401

3b. Phone No. (include area code)
505-325-6800

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1730' FSL, 1930' FEL, Sec. 36, T27N, R03W, N.M.P.M.

5. Lease Serial No.

Jicarilla Contract 95

6. If Indian, Allottee or Tribe Name

Jicarilla Apache

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Jicarilla 95 6A

9. API Well No.

30-039-25442

10. Field and Pool, or Exploratory Area
Blanco Mesaverde PC

11. County or Parish, State

Rio Arriba NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start Resume)	<input checked="" type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

07/26/02 MIRU.
07/29/02 TOH with 2-3/8" tubing. TIH with RBP, set @ 4000'. Swab PC dry. Moved RBP downhole.
07/30/02 Isolate Cliffhouse & Point Lookout zones. Swab back returns. Very little water.
07/31/02 Acidize CH/PL with 500 gals. 15% HCL per zone.
08/01-02/02 Continue swab tests.
08/05/02 TOH with packer. TIH with RBP.
08/06/02 TIH. Clean out 5850' - 5945' with air mist.
08/07/02 TIH. Clean out to RBP @ 6212'. Retrieve RBP. TIH with 2-3/8" tubing, set @ 6085'.
ND BOP. NU wellhead. RDMO. Return to production.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Vicki Donaghey

Title

Production Assistant

Date 08/12/02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by /s/ Patricia M. Hester

Title Lands and Mineral Resources

Date AUG 15 2002

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office