

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored internals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):				38. GEOLOGIC MARKERS		
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
				Ojo Alamo	2348' est.	
				Kirtland	2488' est.	
				Fruitland fma	2767'	
				Pictured Cliffs	3194'	
				Lewis	3352'	
				Chacra	4156'	
				Cliffhouse	4852'	
				Menefee	4972'	
				Point Lookout	5438'	
				Mancos	5841'	
				Gallup	6614'	
				Greenhorn	7365'	
				Graneros	7429'	
				Dakota	7466'	