

37 SUMMARY OF POROUS ZONES: (Show all Important zones of porosity and contents thereof; cored intervals; and all drill -stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Ojo Alamo		2566'	water
Fruitland Coal	2656'	3165'	gas
Pictured Cliffs	3165'	3263'	gas
Mesa Verde	4846'	5821'	gas
Dakota	7531'	7656'	gas

38. GEOLOGIC MARKERS			38. GEOLOGIC MARKERS		
NAME	TOP		NAME	TOP	
	MEAS.DEPTH	TRUE VERT. DEPTH		MEAS.DEPTH	TRUE VERT. DEPTH
San Jose	Surface		Mancos	5821'	
Ojo Alamo	2566'		Tocito Sand	6961'	
Kirtland Shale	2616'		Dakota	7531'	
Pictured Cliffs	3165'				
Lewis Shale	3263'				
Cliff House	4846'				
Point Lookout	5386'				