Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

CHARDOV MOTICES AND DEDODTS ON WELLS

FORM APPROVED
OMB NO. 1004-9135
Expires: November 30, 2000

	EXDITES: NOVEITIBEL 30, 2000
5.	Lease Serial No. NMSF080668
_	

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						1414101 000000				
						6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.						7. If Unit or CA/Agreement, Name and/or No.				
Type of Well     ☐ Oil Well    ☐ Other						8. Well Name and No. SAN JUAN 27-4 UNIT 139M				
2. Name of Operator BURLINGTON RESOURCES O&G CO LP  Contact: PEGGY COLE E-Mail: pcole@br-ipc-com						9. API Well No. 30-039-26539-00-X1				
3a. Address P O BOX 4289 FARMINGTON, NM 87499	3b. Phone No. (in Ph: 505.326.9 Fx: 505.326.9	72		Field and Pool, or Exploratory     BASIN DAKOTA						
4. Location of Well (Footage, Sec., T	<del></del>	15 TUS	- 1	11. County or	r Parish, a	nd State				
Sec 9 T27N R4W NWSE 1910		RIO ARRIB			RIBA CC	IBA COUNTY, NM				
Sec 9 12710 1440 1400 SE 1910	OI OL 17001 LL									
				/						
12. CHECK APPE	ROPRIATE BOX(ES) TO	O INDICATE N	ATURE OF 1	NOTICE, RI	EPORT, OR	OTHER	DATA			
TYPE OF SUBMISSION TYPE OF ACTION										
☐ Notice of Intent	☐ Acidize	☐ Deepen		☐ Producti	Production (Start/Resume)		☐ Water Shut-Off			
	☐ Alter Casing	☐ Fracture	e Treat	☐ Reclama	lamation		☐ Well Integrity			
☑ Subsequent Report	□ Casing Repair	☐ New Co	onstruction	☐ Recomplete			<b>⊠</b> Other			
☐ Final Abandonment Notice	☐ Change Plans	Plug an	d Abandon	☐ Tempora	Temporarily Abandon		Drilling Operations			
	☐ Convert to Injection	☐ Plug Back ☐ Water Disposal								
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  6-27-02 MIRU. TIH w/gauge ring to 8036'. Ran CBL-CCL-GR @ 1500-8030', TOC on 4 1/2" csg @ 2584'. Ran CCL-GR @ 0-1500'. RD.  8-1-02 MIRU. SDON.  8-2-02 ND WH. NU BOP. TIH w/CIBP, set @ 4990'. Attempt to TOOH. Stuck setting tool @ 4965'. TOOH. TIH w/free point to 2511'. TOOH. TIH w/chemical cutter. Load hole w/50 bbl 2% KCl wtr. Chemical cut 4 1/2" csg @ 2510'. TOOH w/58 jts 4 1/2" csg @ 2510'. TOOH w/58 jts 4 1/2" csg & chemical cutter. TIH w/fishing tools. Tag 55' fill. Establish circ. Latch fish. TOOH w/fishing tools & setting tool. SDON.  8-3-02 TIH w/3 7/8" mill. Establish circ. Mill out CIBP @ 4995'. Blow well & CO.										
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #13672 verified by the BLM Well Information System  For BURLINGTON RESOURCES OLG CO LP, sent to the Farmington  Committed to AFMSS for processing by Adrienne Garcia on 08/22/2002 (02AXG0539SE)										
Name (Printed/Typed) PEGGY C	OLE	11	tle REGUL	ATORY ADI	VIINISTRATO	JK				
Signature (Electronic S	Submission)	D	ate 08/20/2	:002						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE										
Approved By ACC	EPTED			IENNE GAR ROLEUM EN		Date 08	8/22/2002			
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conductive the conductive to conductive the applicant to conductive th	uitable title to those rights in th		Office Farm	ington						
<u> </u>										