

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED  
OIL CON. DIV. 1  
DIST. 3

Form approved,  
Bureau of Bureau No. 1004-0135  
Expires August 31, 1985

SUBSIDY NOTICES AND REPORT

(Do not use this form for property to drill or to develop  
an application for permit)

RECEIVED  
OIL CON. DIV. 1  
DIST. 3  
DEC 3 0 1987

See attachment  
1. NAME OF OPERATOR

NAME OF OPERATOR  
Chevron U.S.A. Inc., Room 11111

ADDRESS OF OPERATOR  
P. O. Box 599, Denver, Colorado 80201

2. WELL FORECAST NAME  
West Bisti

3. WELL NO.  
See attachment

4. FIELD AND NAME OF FIELD  
See attachment

5. NAME OF AREA OF OIL  
Bisti Lower Gallup

6. COUNTY OR PARISH  
See attachment

7. STATE  
San Juan New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NATURE OF INTEREST FOR  |                       | SUBSEQUENT REPORT OF    |                  |
|-------------------------|-----------------------|-------------------------|------------------|
| LEASE MATCH INFORMATION | FEED OR ALTER CANNING | LEASE MATCH INFORMATION | REPAIRING WELL   |
| FRACTURE TREAT          | MULTIPLE COMPLETE     | FRACTURE TREATMENT      | ALTERING CANNING |
| FRUIT OR SHELTER        | ABANDON*              | FRUIT OR SHELTER        | ABANDONMENT      |
| REPAIR WELL             | CHANGE PLANE          | REPAIR WELL             |                  |

Other Long term shut-in

DETAIL FOR LT SHUT IN EXTENSIONS

Chevron U.S.A. Inc. requests a one year extension of the long term shut-in status for the wells listed in the table attached. The extension is necessary due to the time required to evaluate a waterflood expansion pilot.

A detailed reservoir study of the West Bisti Unit has indicated that a substantial amount of additional oil can be recovered by revamping the waterflood. In order to determine if the additional oil can be recovered economically, a pilot waterflood expansion is expected to be completed in the First Quarter of 1988. The complete analysis of the pilot is expected to take approximately one year. Well No.'s 123, 141 and 134 have been recently shut in due to their uneconomic status. These wells could also be utilized in revamping the waterflood. A one year shut in status is requested for these wells.

Based upon the results of the waterflood expansion, these wells will be 1) utilized in revamping the complete waterflood in 1989 or 2) plugged and abandoned in 1989.

- 6 - BLM
- 1 - EEN
- 1 - WAC

THIS APPROVAL EXPIRES 12/31/88

*[Signature]*

Technical Assistant

APPROVED  
DATE December 9, 1987  
DEC 2 1987  
James E. Edwards  
MANAGER  
FARMHOUSE RESOURCE AREA

\*See Instructions on Reverse Side

**RECEIVED**

DEC 30 1987

**OIL CON. DIV.**  
**DIST. 3**

| Lease No.       | Well No. | Well Type    | LT S.J.<br>Extension<br>Sundry<br>Due | Location               | Sec., T., R. | Elevation |
|-----------------|----------|--------------|---------------------------------------|------------------------|--------------|-----------|
| 14-20-603-735-A | 100      | Oil Producer | 1/22/88                               | 1,980' FNL, 1,980' FEL | 13-26N-14W   | 6357      |
| NM-013492       | 102      | Oil Producer | 1/22/88                               | 1,980' FSL, 1,165' FWL | 18-26N-13W   | 6463      |
| NM-013492       | 103      | Oil Producer | 1/22/88                               | 660' FSL, 660' FEL     | 18-26N-13W   | 6312      |
| NM-013492       | 109      | Oil Producer | 12/23/87                              | 1,980' FNL, 660' FEL   | 20-26N-13W   | 6376      |
| NM-013492       | 118      | Oil Producer | 12/23/87                              | 660' FSL, 660' FEL     | 20-26N-13W   | 6380      |
| SF-078091       | 121      | Oil Producer | 12/23/87                              | 660' FNL, 1,980' FWL   | 29-26N-13W   | 6572      |
|                 | 123      | Oil Producer |                                       | 660' FNL, 1,980' FWL   | 28-26N-13W   | 6256      |
| SF-078091       | 128      | " "          | 5/19/88                               | 1,980' FNL, 660' FWL   | 28-26N-13W   | 6320      |
| SF-078091       | 132      | " "          | 5/19/88                               | 1,980' FSL, 660' FEL   | 28-26N-13W   | 6231      |
|                 | 134      | " "          |                                       | 1,980' FSL, 660' FEL   | 27-26N-13W   | 6198      |
| SF-081028-A     | 136      | " "          | 1/22/88                               | 660' FSL, 1,978' FEL   | 26-26N-13W   | 6205      |
|                 | 141      | " "          |                                       | 660' FSL, 1,980' FEL   | 28-26N-13W   | 6276      |
| SF-078155       | 146      | " "          | "                                     | 660' FNL, 1,980' FWL   | 35-26N-13W   | 6221      |
| SF-078155       | 154      | " "          | "                                     | 1,980' FSL, 660' FEL   | 35-26N-13W   | 6233      |
| SF-078155       | 159      | " "          | "                                     | 660' FSL, 1,980' FEL   | 35-26N-13W   | 6169      |
| SF-078155       | 161      | " "          | "                                     | 600' FNL, 600' FEL     | 1-25N-13W    | 6179      |
| SF-078155       | 162      | " "          | "                                     | 1,880' FNL, 1,980' FEL | 1-25N-13W    | 6218      |
| SF-078155       | 165      | " "          | "                                     | 660' FSL, 1,980' FEL   | 1-25N-13W    | 6239      |
|                 | 149      | " "          | 12/87                                 | 2,310' FNL, 1,650' FEL | 35-26N-13W   | 6230      |
| SF-078155       | 153      | Injector     | 5/19/88                               | 1,990' FSL, 1,960' FWL | 35-26N-13W   | 6237      |
| SF-078091       | 131      | Oil Producer | 1/22/88                               | 2,200' FSL, 1,400' FEL | 28-26N-13W   | 6210      |
| SF-078091       | 138      | Oil Producer | 1/22/88                               | 990' FSL, 990' FEL     | 27-26N-13W   | 6209      |