

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Texaco Inc.

3. ADDRESS OF OPERATOR
P.O. Box EE, Cortez, CO. 81321

4. LOCATION OF WELL (Report location clearly and in accordance with State requirements.
See also space 17 below.)
At surface
6601G x 6601E

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, CR, etc.)
5763' DF

5. LEASE DESIGNATION AND SERIAL NO.
14-20-0603-8104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo Tribe

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Navajo Tribe "AL"

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Tocito Dome

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 28, T26N, R18W NWPI

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco Inc. proposes to P & A This well because it is uneconomical to produce. The well was shut in in December, 1982. Cumulative production is 79034 BO and 182540 MCF Gas. Well to be plugged and abandoned contingent of Texaco's Management approval (Approximately 90 days).

ABANDONMENT PROCEDURE:

- 1.) Fill hole w/mud.
- 2.) Spot 12 sxs cement plug across Barker Creek Perfs.
- 3.) Spot 10 sxs cement plug @ 5100'.
- 4.) Perf 4-way squeeze shot @ 4500', and squeeze w/30 sx cement. (Leave 8 sx inside 4 1/2" csg.)
- 5.) Perf 4-way squeeze shot @ 3800' and squeeze w/30 sx cement. (leave 8 sx cement inside 4 1/2" csg.)
- 6.) Perf 4-way squeeze shot @ 2800' and squeeze w/30 sx cement. (leave 8 sx cement inside 4 1/2" csg.)
- 7.) Perf 4-way squeeze shot @ 1200' and squeeze w/30 sx cement. (Leave 8 sx cement inside 4 1/2" csg.)
- 8.) Spot 4 sx surface plug in 4 1/2" csg. and 10.5 sx surface plug between 4 1/2" and 8 5/8" casing.
- 9.) Erect Dry hole marker, and clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED Al R. Mann TITLE Area Superintendent DATE 7/9/85

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:
BLM (6) - NMOGCC (3) - JNH-AJS-ARM - Navajo Tribe

*See Instructions on Reverse Side

NMOGCC