		UNITED STAT MENT OF THE		SUBMIT IN TRIPLICA (Other instructions of verse side)	1 re	Form approve Budget Bures EASE DESIGNATION	u No. 42-R142
	ORY NOT	CES AND RE	PORTS (		6. 11	F INDIAN, ALLOTTEE	OR TRIBE NAM
1.	Vise "APPLICA	TION FOR PERMIT-	or such p	oack to a different reservoir.		NIT AGREEMENT NA	ME
ell X GAS WELL OTHER  2. NAME OF OPERATOR						West Pisti Unit	
Gulf Oil Corputation 3. ADDRESS OF OPERATOR					9. w	9. WELL NO.	
Eox 670. Hobbs: New Mexico 88240  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  See also space 17 below) At surface						13.7 10. FIELD AND POOL, OR WILDCAT	
)' FS & WL, Sect	mon 26, 2	26-N, 13-W			11.	SEC., T., R., M., OR B SURVEY OR AREA	LK. AND
14. PERMIT NO.		15. ELEVATIONS (She	ow whether Di	, RT, GR, etc.)	<u></u>	COUNTY OR PARISH	13. STATE
6.	Check Ap	propriate Box To	Indicate N	lature of Notice, Report,	or Other	Data	
NO	OTICE OF INTEN	rion to:		so	BSEQUENT B	EPORT OF:	
TEST WATER SHUT-OFI FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	-	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS		WATER SHUT-OFF  FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Acidiz (NOTE: Report r	ed esults of mu	REPAIRING V  ALTERING CA  ABANDONMEN  altiple completion  Report and Log for	ASING VT*
Pumped 2500 ga				asing over 5-1/2" Returned well to			ns 4966'
Pumped 2500 ga							ns 4966'
Pumped 2500 ga				Returned well to			ns 4966'
Pumped 2500 ga	with 500	gallons of		Returned well to	product		ns 4966'
Pumped 2500 ga	With 500	gallons of L 6 1973		Returned well to	product		ns 4966'
	with 500	gallons of  L 6 1973  CON. COM.  DIST. 3		Returned well to	product		