## LIMITED STATES

DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	SF 078432  6. IF INDIAN, ALLOTTEE OR TRIBE NAME  7. UNIT AGREEMENT NAME	
SUNDRY NOTICES AND REPORTS ON WELLS		
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAM	IE.
1. oil gas X other	Hodges  9. WELL NO.	
2. NAME OF OPERATOR	#2	
SOUTHERN UNION EXPLORATION COMPANY	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR	Ballard Pictured Cliffs	
P. O. BOX 2179 FARMINGTON, N.M. 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec 28-T26N-R8W NMPM	
AT SURFACE: 990' FSL & 990' FEL	12. COUNTY OR PARISH San Juan	13. STATE New Mexico
AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same		New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.	1
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW 6410 G.L.	DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:		
SHOOT OR ACIDIZE  REPAIR WELL  PULL OR ALTER CASING  MULTIPLE COMPLETE  CHANGE ZONES  MAR  BUREAU OF LA FARMINGTON	EIVED 2 3(NOTE: AREport results of m Change on Form 9- AND MANAGEMENT RESOURCE AREA	ultiple completion or zone 330.)
ABANDON* \ \		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Pulled 1" tubing. Cemented  $5\frac{1}{2}$ " casing w/225 sks (380 cu ft) 3-20-84 65/35 Class B/Poz w/6% gel.

Cut off wellhead  $1\frac{1}{2}$  below G.L. & welded on PTA marker.



OIL CON. DIV.

		DI31.	
Subsurface Safety Valve: Manu. and Type	e	Set @	Ft.
			*
SIGNED STEEL VILLE	true and correct TITLE Drlg. & Prod. Suptomate _	March 21,	1984
_//	(This space for Federal or State office use)		
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE DATE	ACCEPTED FO	necond

MINATOR

\*See Instructions on Reverse Side

