5. LEASE N00-C-14-20-503-5034

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo Tribe
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME Navajo Tribal "U"
1. oil gas other Dry	9. WELL NO. 354 100 1514
2. NAME OF OPERATOR 0.T.H.G., Inc.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Tocito Dome Pennsylvanian "D"
c/o A. R. Kendrick, Box 516, Aztec, NM 87410	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA 0-21-T26N-R18₩ 8 8
below.) AT SURFACE: 660' FSL 1980' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	30-045-05715
	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5698 DF
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	
PULL OR ALTER CASING 🗍	(NOTE: Report results of malifies completion or zone change on Form 9–330.)
MULTIPLE COMPLETE	
ABANDON* 🕅	OIL CON. DIV.)
(other) Test Organ Rock formation	DIST. S
including estimated date of starting any proposed work. If well is different measured and true vertical depths for all markers and zones pertinent. Use mast truck and attempt to log the Organ Rock formation from 4. If interest in Organ Rock formation is indicated, will rig up workove usable: set a cement retainer • 5600; squeeze perfs 6138-6143 for possible Helium gas. Complete as an Organ Rock gas well if it approximation in the set of the set o	to this work.)* 300' to 5000'). r unit; confirm casing integrity. If casing is w/40 sx cement.* Test Organ Rock formation
If interest in Organ Rock formation is not indicated or in case of bad casing, the well will be plugged and abandoned with minimal cement as follows: 4300'-4200', 3750'-3650', 2780'-2680', 2080'-1980', 1400'-1200', and 30' 50' 4 at surface.	
A small earthen pit will be needed on location during these operation and levelled when weather permits.	s. The pit will be filled and the location cleaned
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED AGENT	DATE March \$28, 1988
(This space for Federal or State off	ice use)
APPROVED BY TITLE TOTAL CONDITIONS OF APPROVAL, IF ANY:	DATEAPPROVED
CONDITIONS OF AFFROYAL, IF AIVI.	AS AMENDED
1	
*See Instructions on Reverse	april (durande)
MANA	I JUANEA MANAGER

BUREAU OF LAND MANAGEMENT 1235 La Plata Highway Farmington, New Mexico 87401 Phone (505) 327-5344

Attachment to Notice of

Intention to Abandon

Re: Permanent Abandonment

Well: 2 Navajo Tribal"U"

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."

2. Bill Blackard with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 327-5344.

3. Blowout prevention equipment is required.

4. The following modifications to your plugging program are to be made (when applicable): Place 10 Sx plug on top of cement retainer @ 5600' Surface plug is to be Minimum of 50' Cement is to placed down backstide.

Office Hours: 7:45 a.m. to 4:30 p.m.