				/	
Form 9-331 (May 1963)	UNITED STATES				
D	FPARTMENT OF THE INT	SUBMIT IN TRIPLICAT	Form approv	red /	
	EPARTMENT OF THE INT	ERIOR verse side) Thetructions on	re-   Budget Ruse	ion Ma da maia.	
	GEOLOGICAL SURVE	Y	DESIGNATION	AND SERIAL NO.	
SUNDR'	Y NOTICES AND REPORT	TC ON ME	SF-078953		
(Do not use this form	for proposals to drill or to deepen on	IS ON WELLS	6. IF INDIAN, ALLOTTE	E OR TRIBE NAME	
1. Use	for proposals to drill or to deepen or a for PERMIT—" for s	ouch proposals,)			
OIL CAR C					
WELL WELL	7. UNIT AGREEMENT NA	ME			
2. NAME OF OPERATOR	OTHER Injection Well		8. FARM OR LEASE NAB		
Skelly Oil Compa	Skelly Oil Company				
3. ADDRESS OF OPERATOR	4 .	J. W. Goddard			
1860 Lincoln St	9. WELL NO.	ra			
4. LOCATION OF WELL (Report See also space 17 below.) At surface	0	•			
At surface		10. FIELD AND POOL, OR WILDCAT			
			_		
1920' FNL & 640' FWL of Section 11-26N-12W			Uallegos Gal	Gallegos Gallup	
			SURVEY OR AREA	11. SHC., T., R., M., OR BLK. AND SURVEY OR AREA	
14. PERMIT NO.				1 2	
	15. ELEVATIONS (Show whether	er DF, RT, GR, etc.)	Sec. 11-26N- 12. COUNTY OR PARISH	12W	
	6043 * GR	6043° GR			
<sup>16.</sup> Ch	lack Appropriat D. T. L.		San Juan	New Mexic	
,	neck Appropriate Box To Indicate of Intention to:	e Nature of Notice, Report, or (	Other Date		
NOTICE	OF INTENTION TO:			Section 1	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	BUBSEQ	UENT REPORT OF:		
FRACTURE TREAT	MULTIPLE COMPLETE	WATER SHUT-OFF	REPAIRING WE		
SHOOT OR ACIDIZE	ABANDON*	FRACTURE TREATMENT	ALTERING CAS		
REPAIR WELL	<del></del>	SHOOTING OR ACIDIZING		-	
(Other)	CHANGE PLANS	(Other)	ABANDONMENT		
. DESCRIBE PROPOSED OR COMPLY		(NOTE: Report results	of multiple completion on letion Report and Log for	Wall	
proposed work. If well is	ETED OPERATIONS (Clearly state all perting directionally drilled, give subsurface lo	nent details, and give pertinent dates	letion Report and Log form	.)"•Ц	
Work,	See Subditace 10	cations and measured and true vertical	al depths for all markers a	of starting any	
				dones bettl:	
This woll	•				
rura Merr Leached	the economic limit and	no longer is make			
D2	d the economic limit and	rouger is profitab	Le to operate.		
rians are to plug	g and abandon this well	ng 6-33			
First Plug -	- Across Gallup Zone per - 50° inside 5 1/2° cas	8			
Second Plug	= 501 inside 5 7 /or	is. 5166'-5130' filling	g up 50° to 5000	•	
Third Plug -	- 50° inside 5 1/2" cas: 100° plug above top of	ing and 50° above where	e casing is shot	1 <b>.</b> . 1 m. 4	
	100' plug above top of casing is left remaining	Mesa Verde formation	inglede backerat	TU TMO.	
Fourth Plug	casing is left remaining 100' plug at the better	ng through this zone).	producti	on	
* _ug	- ioo. prug at the botto	ng through this zone). om of Ojo Alamo Sand (r	າກໄດດວ່ວນ. ຄ	2	

100' plug at the bottom of Ojo Alamo Sand (unless surface casing is set through the Ojo Alamo Sand).
10 sacks of cement in top of surface casing with dry hole marker.

		, NOV.	4 Z 1757
		U. S. GZOLO	G' AL SUOVE
18. I hereby certify that the foregoing is true and correct	Disi. 8	ji ji	
(This space for Federal or State office use)	District Superin	tendent DATE	Nov. 17, 1967
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	Е	DATE _	