


The FRONTIER REFINING CO.

4040 EAST LOUISIANA AVENUE • DENVER 22, COLORADO



DENVER, COLORADO
General Office

CHEYENNE, WYOMING
Manufacturing

4040 East Louisiana Avenue
Denver 22, Colorado
September 9, 1957

New Mexico Oil Conservation Commission
120 East Chaco
Aztec, New Mexico

Attention: Emery C. Arnold,
Supervisor, District #3

Gentlemen:

Reference is made to your letter of September 6, 1957, concerning the recent completion of our Chartier No. 1, located in Unit "M", Section 4, Township 26 North, Range 12 West, San Juan County, New Mexico, requesting that a corrected Form C-128 be filed.

Apparently your information that the subject well is a producing, or capable of producing oil well is incorrect. On July 9, 1957, we prepared your Form C-104, requesting a gas allowable for this well. Our file does not indicate that you have approved or returned a copy of this form to us. However, you did return Form C-110 to us for this well, which we prepared on July 25th, since it failed to designate the authorized transporter of gas. This form did show that the Chartier No. 1 is shut-in, pending negotiation of a gas sales contract. At the present time, we believe that the Chartier No. 1 will be principally a gas producing well rather than oil and, therefore, believe that the present form C-128 is proper, since it shows a normal gas location.

Yours truly,

Gary W. Hudiburgh,
Land Superintendent

GWH:lma

