

			0	GEI	לאני ל							ROSPECT	
				+ FE3 3	- 1965		H-CO	PTEXO N-CO	STATES) NTEI	BI OB ®	I W III	
				0.00	CION SUE		DIS	7. 3	SURVE	EY (g Ento	b 5 1962	URYEY
				- 1: 7: CEC: C	Page History		OLO:			,	My EE	COLUMN NEW PORT COLOR OF THE LANGE NEW PORT COLOR OF THE LANGE NEW PORT COLOR OF THE	MEXICO.
				-	_	_				. ~	U. S.	SWELL ME	
		A TT 14/51 L 4	CORRECTLY]	LOG	O	F O	IL ()R G	AS	WEI	.L	
			stad 041 &	Gas, Inc	2.	1	21 Add ass	12 To	wer Bui	ldin	B, Denve	r, Colo.	-
	т	Т Соп	solidated-	RWYS]	r tera			51	uarue		
	Location	££	t. S. Ter	Line Ind	ft. {\f	w.} d	# I	ine of	of the w	all avo	d all work	evation rick floor relative to sea ! done there	level)
			tion given her etermined fro		complete	rds.	COLLECT	Tecord .		٤.			
	T) 41.4		1962		Sigi	nea -		7	richief i	K n gir	166T		-
					dition	of t	he well	at abov	ve date.	. 2		62	
	Comme	enced drill	y on this pag	28	,43		Finishe	ed drilli	ing	y -		, 19	
						note g	as by G)						
G	No. 1,	from 2751		to27841		· -	No. 4,	from		 -	to		
G	No. 2,	from 7050	•	to7250'		-	No. 5,	from			to		
	No. 3,	from		. to MM	IPORTAN	 4T V							
	No. 1,	from		. to			No. 3,	from -					
	No. 2,	from		_ to			No. 4,				to		
		Weight	Threads per	B.T. Line	Amount	i	d of shoe		l pulled from		Perforated	Purpos	===
	casing	per foot	inch	Make						See	m- To-	Surface	
9 : 5	5/ 8'	32, 19956 648, 500 1	h g-the red g	20 F 10 1551	270 are 1		ឬមហ្គាល្សៈសេទ្	s ingde a begn d uerini	n the tash - Banaré, j 2 d, gasitio	: stat :•rr-du :•nand	o full, cos trentantes res m es ef e	if uny casing itim, and ner itim,	7 12 100
-	21.14.14 14	r cession, it	atest topportune	10 5876 3	of tree per	65077	सुरारी अस्ति। 	•== <u>=</u>	নভাগাত ₍ ত q)	elan ti	(6 도 _국 2실하는 4% 년	and Millian and gre	
					MAKO					3 1898	a 1, 10 000	BACHA BACKATAT AND	er
		MUDDING AND CEMENTING RECORD Mud starting Amount of mud used											
	Size casing	Where s	et Numi	per sacks of een			hod used		Aud gravity	_		or interest	
ž	5/8"	358 7270		plus 100	1			a i financia		- (
MAGKE	1/2"		150 ex.	plus 100 50/50 Pa	981X - E0	<i>I</i> -U							
FOLD			Material -Ge		PLUGS	ANI Leng	th	TERS		Dept	th set	254.	
Ħ	Heavi Adap	ıng piug— ters—Mat	erial	sent-		Size				- -			
5		ter frac			SHOO	TIN	G REC	ORD Date	Depth sh	i		n cleaned out	
	Si:	ze S	45,000f	Explosive us		Quan							
	2754* 7053*	- 2783¹ - 7244¹	45,000# 155,000#	sand, 33	9,500 g	1	water,	1,00	0.gal	icid.			
				1	T	OOL	S USEL)					
	Rota	ry tools w	ere used from	•	feet t	0 -72	771	feet,	and from		fee fee	t to t to	_ feet
	Cable	e tools wer	e used from	 	reet t	:0 ₁ - D À	THE C						
	- Jax	mary 23		, 182								, 10	
			ction for the % water; and				bar	reis oi	Gravity, ^c	·men ·Bé	/0		
			$\frac{90}{1}$ cu. ft. per 2	DIK.	4/33 m	IFD	Gallon					gas	
			sure, lbs. per	so, in. DK	2185			_					
			ing Co.		i	EIV1R°I	LOYEES					, D)riller
	nur	OH DITT			_, Driller							, I)riller
			· 		FORM	1	ON RE	CORD		ORMA'	TION		
	1	FROM—	то-		UTAL FEE								
	P	erforat i	ons:	, ;				FC	RMATION	TOP	©; ∖‱g))	
		7053	7084				Pict	ured (Fm. Sd.	26 54 ' 2713 '	(#4266) (#4207)	
		7122 7138	7132 7152					verde			4235'		
		7183 7200	7186 7205				Me	iffhou nei ce			44831	(#2437) (#1972)	
		7221	7244				Mand		rout		5 155'	(/1765)	
		2754	2783				Gall	up nhorn			6952	(# 875) (- 32)	
							Dako	ta			7050'	(- 130)	

. William John	NOM	FORMA		 	LOTAL FEET	.	-от	-MOH-
			-					
	125. 3							
			× ·	v. Pisa				
	.	,		8 - 1				
		e de la companya de		% · *				
		:						
					er year			
				,				
								1 :
								-1
						· , ,		
-		······		i Agrico	**************************************		internation	
						į	at the transfer	
				eks Solomoris Solomoris				
			•			,		

It is of the greatest importance to have a complete history of the well. Please state in detail the dates of redrilling, together with the reasons for the work and its results. If there were any changes made in the casing, state fully, and it any casing was "sidetracked" or left in the well, give its size and location. If the well has been dynamited, give date, size, position, and rumber of shots. If plugs or bridges were put in to test for water, state kind of material used, position, and results of pumping or bailing.

CAR CHARLES FOR SOMES

As a second to the facility of them. I see any of the man Tipliched a link of

 f_{T} T

tion of the said

DRILLING AND COMPLETION HISTORY

CONSOLIDATED OIL & GAS, INC.

CONSOLIDATED-HALE NO. 3-26

San Juan County, New Mexico January 31, 1962

Location:

990' F/NL & 790' F/EL Section 26

T26N-R8W NMPM

Elevation:

6908' Ground

6920' KB - all measurements from KB

Spud:

November 28, 1961

Drilling Completed: Well Completed:

December 23, 1961 January 2, 1962

Total Depth:

7277' Drilled 7254' Plug Back

Casing:

Surface -

9 5/8" 32# H-40 cemented at 358'

w/200 sx. 2% HA5 cement.

Production -

5 1/2" 15.5# & 17# J-55 cemented at 7270' w/200 sx. 4% gel cement w/1/2 cu. ft. Strata-Crete per sack thru shoe and 150 sx. 4% gel 50-50 Pozmix cement thru stage collar at 2806'.

Tubing-

1 1/2" EUE J-55 set in Model "D" packer

at 70041

l" regular hung at 2027'

Logs:

Schlumberger Induction-Electric

Cores and Drillstem Tests:

None

Formation	Tops:	(Log)
-----------	-------	-------

Pictured Cliffs	Fm.	2654' 2713'	(+ 4266) (+ 4207)
Mesaverde	Su.	2713	(14207)
Cliffhouse		42351	(+ 2685)
Menefee		44831	(+ 2437)
Pt. Lookout		49481	(+ 1972)
Mancos		5155'	(* 1765)
Gallup		6045	(~ 875)
Greenhorn		6952'	(- 32)
Dakota		7050'	(- 130)

Producing Perforations:

DK	PC				
7053' - 7084'	2754' - 2783'				
7122' - 7132'					
7138' - 7152'					
7183' - 7186'					
7200' - 7205'					
7221' - 7244'					

Treatment:

Dakota - Sand water frac with 155,000# 10-20 and 20-40 mesh sand, 139,500 gal. water, 1000 gal. acid in three stages.

Pictured Cliffs - 45,000# 10-20 mesh sand and 35,000 gal. water.

Initial Potential:

Flow volume thru 3/4" choke:

Dakota - 2755 MCFD

Pictured Cliffs - 722 MCFD

WELL:

CON-HALE 3-26

990' F/NL & 790' F/EL, Section 26-T26M-R8W

FIELD:

Basin Dakota - Ballard Pictured Cliffs

COUNTY:

San Juan STATE: New Mexico

ELEVATIONS:

6908' GD

11/29/61

Depth 180'. Drilling 13 3/4" hole, spudded at 10 p.m. 11/28/61. Mud 8.9. Vis. 60. Dev. 1/2° at 100'.

11/30/61

Depth 445'. Drilled 358' of 13 3/4" surface hole. Ran 345' of 9 5/8" casing set at 355' KB. Cemented with 200 sx. regular with 2% HAS. Plug down at 3 p.m. Good circulation throughout job.

12/1/61

Depth 2173'. Tripping for Bit 3. Drilled 1728' of sand and shale. Drilling with water. Day. 2° at 950', 1 3/4° at 1400', 1 3/4° at 1900'.

12/2/61

Depth 3103'. Drilling with Bit 4. Drilled 930' of sand and shale. Drilling with Water. Dev. $1/2^{\circ}$ at 2400° , i $1/4^{\circ}$ at 2900° .

12/3/61

Depth 3233'. Drilling with Bit 7. Drilled 120' of sand and shale. Mud 9.5. Vts. 45. Water loss 9.2. (Lost cone on bit, fish to recover, mudded up while fishing.)

12/4/61

Depth 3636'. Tripping for Bit 9. Drilled 432' of sand and shale. Mud 9.3. Vis. 38. Water loss 12.

12/5/61

Dapth 3940'. Tripping for Bit 11. Drilled 304' of sand and shale. Maid 9.6. Vis. 36. Water loss 12. Dev. 1 $1/4^{\circ}$ at 3600'.

12/6/61

Depth 4137'. Drilling with Bit 12. Drilled 197' of sand and shale. Mud 9.5. Vis. 36. Water loss 11. Mud cake 2/32. PH 8.

WELL:

CON-HALE NO. 3-26

12/7/61

Depth 4369'. Drilling with Bit 14. Drilled 232' of sand and shale. Mud 9.8. Vis. 36. Water loss 11.6. Mud cake 2/32, PH 8.

12/8/61

Depth 4601'. Tripping for Bit 16. Drilled 232' of sand and shale. Mud 9.6. Vis. 36. Water loss 12.2. Mud cake 2/32. PH 8.2.

12/9/61

Depth 1890'. Drilled 289' of sand and shale. Drilling with Bit 18. Mad 9.8. Vis. 36. Water loss 12.4. Dev. 1 3/4' at 4725'.

12/10/61

Depth 515P. Drilled 261 of sand and shale. Tripping for 15t 20. Mud 9.9. Vis. 36. Water loss 12.4.

12/11/61

Depth 5394. Drilled 240 of sand and shale. Drilling with Bit 21. Mad 10. Vis. 42. Water loss 12.4.

12/12/61

Depth 5595'. Drilled 212' of sand and shale. Drilling with Bit 22. Mid 10. Vis. 50. Water loss 9.

12/13/61

Depth 5832'. Drilled 237' of sand and shale. Mud 10. Vis. 52. Water loss 8.9. Drilling with 13i 23.

12/14/61

Depth 6010'. Drilled 178' of sand and shale. Drilling with Bit 25. Mud 9.7. Vis. 47. Water loss 13.6.

12/15/61

Depth 6260'. Drilling with Bit 26. Drilled 250' of sand and shale. Mud 9.9. Vis. 48. Water loss 13.2.

WELL:

CON-HALE NO. 3-26

12/16/61

Depth 6473'. Tripping for Bit 28. Drilled 213' of sand and shale. Mud 10. Vis. 52. Water loss 11.2.

12/17/61

Depth 6597'. Drilling with Bit 29. Drilled 124' of sand and shale. Mud 10. Vis. 47. Water loss 11.8.

12/18/61

Depth 6793'. Drilling with Bit 30. Drilled 197' of sand and shale. Mud 10. Vis. 46. Water loss 11. Mud cake 2/32. PH 10. Sand content 1/2%.

12/19/61

Depth 7005'. Drilling with Bit 31. Drilled 212' of sand and shale. Mud 10. Vis. 45. Water loss 13.7. Mud cake 2/32. PH 10.

12/20/61

Depth 7148'. Drilled 143' of sand. Tripping for Hit 33. Mud 10. Vis. 67. Water loss 10. PH 8. Estimated top of Graneros by drilling time, 7004'.

12/21/61

Depth 7220'. Drilled 72' of sand. Drilling with Bit 34. Mud 10.2. Vis. 65. Water loss 10.6. Mud cake 2/32. PH 8.5. Projected TD 7240'.

12/22/61

Depth 7261. Tripping for Hit 36. Mtd 10. Vis. 75. Water loss 7.8. Mtd cake 2/32. PH d. Drilled to 7240' (driller's TD), rigged up Schlumberger, ran HES log. Logger's TD 7248', log top of Graneros 7050'. Logged to surface. Went back in with bit drilled 21' of hard sand, drilling time varying from 9 to 30 minutes per Foot

Page 4

Well:

CON-HALE NO. 3-26

12/23/61

Depth 7270. Drilled 9 of sand and shale. Bit torqueing up would not make any more hole. Pulled bit, found one cone locked. Ran Schlumberger log. Logger's TD 7277. Came out of hole laying down drillpipe.

12/24/61

Ran 219 joints, 5 1/2" casing. 113 joints (3808.98') 17# on bottom, 83 joints (2659.77') 15.5# S.T.& C., 21 joints (752.46') 15.5# L.T.& C., 2 joints (86.40') 17# L.T.& C. for a total of 7299.61'. Out off 30.31' for total of 7259.31' set at 7270.31' KB. Float shoe at 7268.81', float collar at 7201.52', stage collar at 2669.41'.

Hit small bridge at approximately 100' off bottom, worked through bridge found TD at 7374'. Backed off 4' off bottom to hook up circulating head, after hooking up circulating head, pipe was stuck, broke circulation at 650 PSIG, good circulation at 450 PSIG. Circulated for 45 minutes while attempting to free pipe. Could not free pipe. Cemented lower stage with 200 sx. regular cement with 48 gel. with 1/2 cu. ft. Strata-Crute per sack, good circulation throughout job. Over displaced plug 2 bbls. Did not hump, released pressure float held OK. Plug down at 6 p.m. Cemented second stage Pictured Cliffs fermation through stage collar with 150 sx. 50-50 Pozmix with 4% gel. Good circulation throughout job, bumped plug with 2200 PSIG, held OK. Released pressure, held OK. Plug down at 10 p.m. Cut off pipe, released rig at 12 midnight.

12/25/61

woc.

12/26/61

WOC. Hauling frac water.

12/27/61

Rigging up rotary rig for completion. Preparing to go in hole with tubing to clean out to ${\rm PBTD}$.

CON-HALE NO. 3-26

12/28/61

Drilling on hard cement at 7225'. Picked up tubing, found 15' of cement on top of DV collar. Drilled DV collar at 2860'. (By tubing measurement 2866'). Pressured up on casing to 1800 PSIC by rig pump, held OK. Pressured up with Dowell to 2500 PSIG, held OK. Ran tubing to bottom, found 25' of cement on top of float collar, drilled float collar at 7200'. (By tubing measurement 7204'.)

12/29/61

Rigging up Dowell to frac second stage. Cleaned out to PBTD of 7254', pressure up to 3500 PSIG for 10 minutes, held OK. Spotted 1,000 gal. 15% mud acid, came out of hole with tubing. Ran cement and correlation logs over Dakota and Pictured Cliffs formations. Found good cement over both sections. Perforated from 7221'-7244', 7200'-7205' with 4 jets and 2 bullets per foot. Soaked away acid in three stages 20 minutes apart, with injection pressures as follows: breakdown, 2200-1800 PSIG; first stage 1700 PSIG; second stage 1750 PSIG; third stage 1400 PSIG. Fraced lower Dakota as follows:

All pumps on line, 2600 PSIC, 40 BPM. Broke back to 2600 PSIG, started sand at 1/2 lb. per gal. for 2 minutes then went to 1 lb. per gal. Sand on perfs, broke back to 2500 PSIG, 42 BPM. 10,000# sand in, 2550 PSIG, 32 BPM. Lost one Allison, air locked, using three only. 20,000# sand in, 2300 PSIG, 34 BPM. 30,000# sand in, 2150 PSIG, 35 BPM, dropped 20 balls. balls on perfs, 100# increase, dropped 10 more balls. 40,000# sand in, 2400 PSIG, 33 HPM, second stage balls on, no action, dropped 10 more balls. 50,000# sand in, 2450 PSIG, 32 HPM, dropped ten balls. Third stage balls on, got 100# increase to 2550 PSIG. 60,000# sand in, started flush at 2550 PSIG. Fourth stage balls on, no action. Finished flush at 2850 PSIG, instant shul-in pressure 2000 PSIG, 15 minute shul-in 1650 PSIG.

Frac Summary:

10,000# 40-60 mesh sand 50,000# 20-40 mesh sand 61,500 gal. water treated with J-100 gel 50 frac balls in four stages Minimum pressure 2150 PSIG Maximum pressure 2850 PSIG Average rate 33 HPM

Page 6

WELL:

CONHIALE NO. 3-26

12/29/61 Confid.

Dan Guiberson bridge plug set at 7193'. Perforated from 7183'-7186', 7138'-7152', 7122'-7132' with 2 jets and 2 bullets per foot. Had communication.

12/30/61

Fraced middle Dakota as follows:

All pumps on line, 3100 PSIG, 35 HPM. Broke back to 2900 PSIG. Started sand at 1 lb. per gal. 10,000# sand in, 2600 PSIG, 42 HPM. 20,000# sand in, 2650 PSIG, 41 HPM, went lo 1 1/2 lbs. per gal. 33,000# sand in, dropped 20 balls, 2600 PSIG, 42 HPM. At 40,000# sand in, 2700 PSIG, no ball action. At 45,000# sand in, 2750 PSIG, 39 HPM. At 50,000# sand in, 2800 PSIG. At 60,000# sand in, 2900 PSIG, 38 HPM. Started flush, lost two pumps, flushed with two pumps at 22 HPM and 2700 PSIG, finished flush at 2750 PSIG. Instant shut-in pressure 1900 PSIG, 15 minute shut-in, 1600 PSIG.

Frac Summary:

60,000# 20-40 mesh sand 44,000 gal. water treated with J-100 gel. Minimum pressure 2000 PSIG Maximum pressure 2900 PSIG Average rate 37.5 BPM 20 frac balls in one stage

Uridge plug at 7100'. Shut down rig, waiting on frac water.

12/31/61

Waiting on frac water.

1/1/62

Broke tower at 7 a.m. Went in hole with 2 1/2" tubing, found sand at 5980', 120' of fill up. Circulated out sand, cleaned out to 7100'. Spotted 750 gal. 15% mud acid, perforated with 2 jets and 2 bullets per foot 7053'-7084' (no apparent communication). Squeezed acid in 3 stages 20 minutes apart. Break down 2200 PSIG to 1800 PSIG, second stage 1800 PSIG, third stage 1600 PSIG. Fraced upper Dakota as follows: (3 Allisons)

WELL:

CON-HALE NO. 3-26

1/1/62 Cont'd.

All pumps on line, 2600 PSIG, 30 BPM, started sand at 1# per gal. Sand on perforations 2400 PSIG, 32 BPM. 10,000# sand in, 2400 PSIG, 32 BPM. Dropped 10 balls. 15,000# sand in, 2400 PSIG, 31 BPM, dropped 10 balls. First stage balls on perfs, 100# increase to 2600 PSIG. Second stage balls on, 100# increase to 2600 PSIG. 22,000# sand in, rate 28.5 BPM, dropped 10 balls. 25,000# sand in, rate 28.5 BPM, dropped 10 balls. 25,000# sand in. 2800 PSIG, dropped 5 balls. Balls on perfs, increase to 3000 PSIG, 26 BPM. 30,000# sand in, stopped 20-40 sand started 10-20 at 1# per gal., rate 25 BPM, 3100 PSIG. At 31,000# sand in, pressure broke back to 3000 PSIG, last frac balls on perfs, 3400 PSIG, 23.5 BPM. Finished flush 3400 PSIG. Instant shut-in 2700 PSIG, 15 minute shuf-in 2000 PSIG.

Frac Summary:

30,000# 20-40 mesh sand 5,000# 10-20 mesh sand 34,000 gal. water treated with J-100 gel. Minimum pressure 2400 PSIG Maximum pressure 3450 PSIG Average rate 26 BPM Dropped 35 frac balls in four stages

Lubricated in bridge plug, set at 2900'. Perforated Pictured Cliffs 2754'-2783'. Fraced PC as follows:

Break down 1700 PSIG, all pumps on line, 1400 PSIG. 40 BPM. Started sand at 1# per gal. 5,000# sand in, 1100 PSIG, 48 BPM. 10,000# sand in, 1100 PSIG, 48 BPM, dropped 10 balls. Went to 1 1/2# per gal., no action on balls. 20,000# sand in, 1050 PSIG, 50 HPM, went to 2# per gal. Dropped 10 balls, no action. 40,000# sand in, 1000 PSIG, 50 BPM. 45,000# sand in, 1000 PSIG, 50 BPM. Sand in, 1000 PSIG, 50 BPM. 45,000# sand in, 1000 PSIG. Instant shut-in 550 PSIG, 15 minute shut-in 400 PSIG.

Frac Summary:

45,000# 10-20 mesh sand
35,000 gal. water treated with J-100 gel.
Minimum pressure 1000 PSIG
Maximum pressure 1400 PSIG
Average rate 48 BPM
Dropped 30 balls in three stages

Page 8

WELL:

CON-HALE NO. 3-26

1/1/62 Cont'd.

Left well shut-in for one hour while rigging up. Went in with 2 1/2" EUE to clean out to PHTD. Drilled bridge plug at 2900". PC took approximately 100 bbls. water, got some flow back while drilling plugs at 7100" and 7100". Cleaned out to PHTD of 7254", during clean out lost approximately 250 bbls. water.

1/2/62

Running 1 1/2" tubing. Came out of hole laying down 2 $7/\kappa^n$ tubing, ran Baker Model "D" packer set at 7010'.

1/3/62

Shut-in, waiting on swabbing unit. Ran 214 joints (6085.13) 1 1/2" FUE tubing plus 8.36" subs and mandrill for a solut of 6993.46' set at 7004.49' KH, in Baker Model D packer set at 7010' KB by wire line measurements. (Note: Had to reset correlation log 5' deep to tie in with open hole log.) Found 8' of sand on top of packer, circulated off sand, landed with 7000% tubing weight on packer. DK dead after landing, lost 150 bbls. water to Pictured Cliffs while running tubing. Pictured Cliffs taking water and kicking strongly. Ran 82 joints (2710.68') of 1" regular tubing set at 2721.165' KB. Jet collars at 2325' and 2027' KB. Released rig at 11 p.m. Dakota and Pictured Cliffs dead and shut-in.

1/4/62

Shut-in, dead. Tearing down and moving off rig. $U_{\rm nable}$ to get swabbing rig to location, bad roads. Will move on tomorrow after moving off completion rig.

<u>1-5-62</u>

Both somes are shut in. Yesterday the Dakota kicked off by itself. Flowing strongly -- very wet. Picture Cliff also gasing slightly. Had to shut both zones in while moving off rig. Will reopen day after rig completes move.

1-6-62

Howing out rotary rig. Blew Dakota four hours. Well heading making heavy amounts of oil and water. Unable to obtain good gauge. Picture Cliff dead. Twenty pounds casing pressure.