

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Federal <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name Huerfano Unit
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name Huerfano Unit
3. Address of Operator Box 990, Farmington, New Mexico 87401	9. Well No. 151-Y
4. Location of Well UNIT LETTER <u>C</u> <u>1140</u> FEET FROM THE <u>North</u> LINE AND <u>1800</u> FEET FROM THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>26N</u> RANGE <u>10W</u> NMPM.	10. Field and Pool, or Wildcat Undesignated Gallup
15. Elevation (Show whether DF, RT, GR, etc.) 6783' GL	12. County San Juan


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> <u>Dakota</u> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <u>Recomplete in the Gallup formation</u> <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is planned to plug and abandon the Dakota formation and recomplete this well in the Gallup formation as follows:

Pull tubing and set a cast iron retainer at 6640', squeeze the Dakota perforations (6740-60') w/75 sacks of cement.

Selectively perforate and sand water fracture the Gallup formation.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	TITLE <u>Petroleum Engineer</u>	DATE <u>9-9-70</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>Sup. Dist. 11</u>	DATE <u>9-11-70</u>
CONDITIONS OF APPROVAL, IF ANY:		