## **NEW MEXICO OIL CONSERVATION COMMISSION** Santa Fe, New Mexico

## **MISCELLANEOUS NOTICES**

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below			
Notice of Intention to Change Plans		Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper
Notice of Intention to Plug Well	xxx	Notice of Intention to Plug Back	Notice of Intention to Set Liner
Notice of Intention to Squeeze		Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)
Notice of Intention to Gun Perforate		Notice of Intention (Other)	Notice of Intention (Other)
OIL CONSERVATION COM SANTA FE, NEW MEXICO	MISSION	Farmington, New Mexico	October 24, 1961
onwin i b, New Mexico		(Place)	(Date)
Gentlemen:  Following is a Notice of In	ntention to do	certain work as described below at the	Indian "O"
AL PASO	MERCHINE!	GAS COMPANY	1
NE NE (Comp	any or Operator	28N 3W	Well No. in (Unit)  Blanco Mesa Verde & (Unit)  Wildcat Pictured Cliffs Peo
(40-acre Subdivision)	Sec	, T, NMPN	A., WIIGHT FICTORIES Peo
manust:	(FOLLOW		REGULATIONS)  med & abandoned in the followsing
1. Spot a 20 sack 2. Spot a 306' cam 3. Determine 5 1/2 4. Spot a 100' cam	ement plug	instructions in the rules and ction this well will be plugg tug on bop of bridge plug at from 3914-3608' to cover per free point and cut casing. across cut-off, pull casing. ing with a 4" x 4' permanent.	regulations)  red & abandoned in the following  3950'.  f. int. 3864-3658'.  type dry hole marker in top of
1. Spot a 20 sack 2. Spot a 306' cam 3. Determine 5 1/2 4. Spot a 100' cam 5. Spot a 10 sack surface pipe. 6. Clean location.	cement plug "casing ent plug cament pl	instructions in the rules and ction this well will be plugg to get from 3914-3608' to cover per free point and cut casing.  across cut-off, pull casing.  across cut-off, pull casing.  across cut-off, pull casing.  across cut-off, pull casing.  By Original S	regulations)  red & abandoned in the following  3950'.  f. int. 3864-3658'.  type dry hole marker in top of  RECEVED  OCT 26 1961  OCT 26 1961  OIL CON. CCM.  OIL CON. 3  Company or Operator  Signed F. H. WOOD
1. Spot a 20 sack 2. Spot a 306' cam 3. Determine 5 1/2 4. Spot a 100' cam 5. Spot a 10 sack surface pipe. 6. Clean location.  Approved	cement plug "casing ent plug cament pl	instructions in the rules and etion this well will be plugged by the plugged by the state of the plugged by the state of the plugged by the cover perfect point and cut casing.  Across cut-off, pull casing.  By Original Separation Petrol	regulations)  red & abandoned in the following  3950'.  f. int. 3864-3658'.  type dry hole marker in top of  RICEVED  OCT 26 1961  OCT 26 1961  OCT 26 1961  OUL CON. CCM.  Signed F. H. WOOD  Leum Engineer
1. Spot a 20 sack 2. Spot a 306' cam 3. Determine 5 1/2 4. Spot a 100' cam 5. Spot a 10 sack surface pipe. 6. Clean location.  Approved	cement plug "casing ent plug cement pl	instructions in the rules and etion this well will be plugged by the plugged by the cover per free point and cut casing.  across cut-off, pull casing.  across cut-off, pull casing.  across cut-off, pull casing.  By  Original Send	regulations)  red & abandoned in the following  3950'.  f. int. 3864-3658'.  type dry hole marker in top of  CTLLVED  OCT 26 1961  OCT
1. Spot a 20 sack 2. Spot a 306' cam 3. Determine 5 1/2 4. Spot a 100' cam 5. Spot a 10 sack surface pipe. 6. Clean location.  Approved	cement plug "casing ent plug cement pl	instructions in the rules and etion this well will be plugged by the plugged by the state of the plugged by the state of the plugged by the cover perfect point and cut casing.  Across cut-off, pull casing.  By Original Separation Petrol	regulations)  red & abandoned in the following  3950'.  f. int. 3864-3658'.  type dry hole marker in top of  CTLLVED  OCT 26 1961  OCT