Form 3160-4 (July 1992)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN DUPLICATE (See other instructions on reverse side)

FORM APPROVED OMB NO. 1004-0137 Expires: February 28, 1995

	BUREA	AU OF LAND	MANAGEME <b>N</b>	$J_{l,\infty}$	$III \cap$	11	5. LEASE	DESIGN	ATION AND	SERIAL NO.	
							SFC	SF 079294			
WELL COMPLETION OR RECOMPLETION REPORT AND LOG *								6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
1a. TYPE OF WELL							7. UNIT	AGREEME	ENT NAME		
	OIL \	WELL	GAS WELL	. 🛛	OTHER [		San	Juan 2	8-7 Unit		
b. TYPE OF COMPLETION:								8. FARM OR LEASE NAME, WELL NO			
NEW	WORK	DEEP-	DIFF.	<del></del> a	۲	<del></del>	San	luan 2	8-7 Unit :	#10	
WELL OVER EN RESVR. OTHER  2. NAME OF OPERATOR									- 7 Onn		
								ELL NO.			
CONOCO INC.  3. ADDRESS OF OPERATOR								39-072			
								10. FIELD AND POOL, OR WILDCAT			
P.O. Box 2197, DU 3065, Houston, TX 77252-2197 (281) 293-1613  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements) *								Blanco Picture Cliffs  11. SEC., T., R., M., OR BLOCK AND SURVEY OR			
At surface 990' FSL & 1120' FWL, UNIT LETTER " M"  At top prod. Interval reported below								AREA			
At total depth								Sec. 36, T28N-R7W			
		14. PERMIT NO.			DATE ISSUED		12. COU	12. COUNTY OR PARISH 13. STATE			
15. DATE SPUDDED	16 DATE TO E	PEACHED	17 DATE COM	1 (0 = = +++++		40 515) 405		Arriba Co		NM NM	
is the second of								ETC) •	19. ELEV	. CASINGHEAD	
20. TOTAL DEPTH, M	D & TVD	21 PLUG	BACK T.D. MD. & TV	-19-99	22 IE MI II	61 TIPLE COMPL. H	19' DF	23. IN	TERVALS D	DILLED DY	
		2111 230,	DATOR T.D. W.D. & TV	J	ZZ. II WICE	TIFLE COMPL. A	CVVIVIAINT		TARY	CABLE	
			2882'		ļ			ŦC	ools 🔈	TOOLS	
24. PRODUCING IN	TERVAL(S) OF THIS	COMPLETIO	N - TOP, BOTTOM, N	NAME (MD A	AND TVD)*		-		25 WA		
2774' – 2828' Blanco Picture Cliffs											
26. TYPE ELECTRIC	AND OTHER LOGS	RUN			***	· · · · · · · · · · · · · · · · · · ·			27. WA	S WELL CORED	
	Bond Logs and	Casing I							-		
28. CASING SIZE/GRADE	WEIGHT, L	D/ET	CASING I	RECORD (F	Report all string						
10 3/4"			211'	+	HOLE SIZE TOP OF CE		200 SXS				
7" 23				_	8 3/4"		225 CVC : 13				
·							225 5 \ 5 \ . \ \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ \ . \ \ \ . \ \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ . \ \ \ . \ \ \ . \ \ \ \ . \ \ . \ \ \ . \ \ \ \ . \ \ \ . \ \ \ \ . \ \ \ \ . \ \ \ \ \ . \ \ \ \ . \ \ \ \ \ . \ \ \ \ \ . \ \ \ \ \ \ \ . \ \ \ \ \ \ . \				
29.	RECORD				30.		TUBING RECORD				
SIZE	TOP (MD)	BOTTON	(MD) SACKS	CEMENT •	SCREEN		SIZE 2 3/8"	<del></del>	SET (MD)	PACKER SET (MD)	
		<del> </del>			<del> </del>		2 3/0		639'	<u> </u>	
31. PERFORATION	RECORD (Interval, s	ize and numbe	er)		32.	ACID. SHOT	FRACTURE,	EMENT:	का महत्त्व ह	10	
DEPTH INTERVAL (											
See attached summary.											
								DE	C 1 3 1	999	
20.4						···		<u> </u>	11.00		
33. * PRODUCTION  DATE FIRST PRODUCTION PRODUCTION METHOD (Flowing, gas lift, pumping - size, and type of pump)								WELL'STATES (Producing or shut-in)			
11-19-99	Flow		···oo ( / /ow///g, guo //	it, painping	Size, and type	от рыпір)			DHC#23		
DATE OF TEST	HOURS TESTED	CHCKE SIZ		FOR TEST	OIL - BBL	GAS - I		WATER -		GAS - OIL RATIO	
11-11-99	24 hrs.	1/2'	PERIOD		0	990	MCFPD	10	bbls		
FLOW. TUBING	CASING PRESS		CULATED 24 - HR	OIL - BBL	PPD FOF	CAS MCE	I VALA TI	ER - BBL		DIL GRAVITY - API	
PRESS		RAT	E	CCEP	I FO FOR	RECORL			(	CORR)	
150#	0				EC 1 3	990 MCF		10 bb			
						1201 Time Sold By					
V Victor Barrios w/Key Energy 35. LIST OF ATTACHMENTS FARMINGTON DISTRICT D. FICT										ergy	
TW HM											
Summary  36 Lhereby certify th	at the foregoing and	attached info-	nation is complete	d correct a-	dotor-in-d	m all available	20140				
36. I hereby certify that the foregoing and attached information is complete and correct as determined from all available records											
SIGNED VILLA VOLTONA ISLINOSIA ISLIN											
SIGNED TITLE VERLA JOHNSON, As Agent for Conoco Inc. DATE 11-24-99											

## CONOCO INC. San Juan 28-7 Unit #10 API #30-039-07223 990' FSL & 1120' FWL, UNIT LETTER "M"

990' FSL & 1120' FWL, UNIT LETTER "M" Sec. 36. T28N-R7W

10/28/99 Road rig to location. Rig up spot all equipment. Rig up pump & pit. Check wellhead pressures. Tbg - 160 psi and Csg - 160 psi. Blow well down. NDWH & NUBOP. Rig up to pull 2 3/8" tubing. Tubing is stuck. Rigged up Weatherford Freepoint, RIH with freepoint tool. Could only run tool to 2340'. POOH and pumped 15 BBLS water. RIH with sinker bars, tagged obstruction @ 2365'. Rigged down Weatherford wireline. From impression on sinker bars, looked like something flat, possible plunger stop that may have moved up the hole. Scheduled Expert slickline to try and fish obstruction.

10/29/99 Rigged up Expert Wireline services. Fished Collar set Plunger Stop @ 2365'. NOTE: ACCORDING TO WELL RECORDS PLUNGER STOP SET @ 4795'. STOP HAD MOVED UP THE HOLE TO 2365'. STOP HAD MOVED UP THE HOLE 2430'. Rigged up Weatherford freepoint tool. Set tool @ 4580'. Tubing was stuck, pulled up the hole and found tubing free @ 4412'. Cut 2 3/8" tubing 4390'. POOH with 2 3/8" tubing. Total tubing 141 jts. plus cut off piece. End of 7" casing @ 4331'. RIH with 2 3/8" tubing and 7" casing scrapper. Run scrapper to 4277'. POOH with 2 3/8" tubing and 7" casing scrapper.

Talked with Steve Mason @ BLM about leaving tubing stuck in the open hole, it was approved by Steve Mason 10/29/99. I also discussed our P & A plans for the MV, everything OK by the BLM 10/29/99. I also left a message at the BLM giving the time that plugs and cement were to be pumped on 11/1/99. RIH with 2 3/8" tubing and Hallib 7' CIBP, Set CIBP @ 4278'. Released setting tool. Started loading hole with KCL water, just about the time the hole was about to load; the casing went on a vacuum. Went back to try and tag the plug, the plug went down the hole. Rigged up Blue Jet wireline and set Hallib 7" wireline set CIBP @ 4282'. RIH with dump baler, and dumped baled 5' of cement on top of CIBP. Will let cement set thru the night and spot the rest of the cement with tubing tomorrow. Notified BLM @ 599-8907 left message @ 3 PM 11/1/99. Notified about cement plug job.

Pumped 5.5 bbls cement slurry. Pumped @ 14.5 ppg. Total cement pumped 22 sks Type 3. Total cement plug 150'. Casing was full and circulated the entire job. POOH with 2 3/8" tubing. Tested casing to 500 psi. OK. Rigged up Blue Jet ran Gamma Ray/ CCL/ CBL log from 3050' to 2000'. Ran CBL log with 500 psi on casing. TOC at approx 2930'. Log indicates tight spots @ approx 2395' and 2000'. Craig Moody talked to Jim Lovato @ BLM about changing procedure, ALL CHANGES APPROVED BY JIM LAVATA WITH BLM 11/2/99 @ 2PM. 599-6367. Rigged up Blue Jet, set wireline set CIBP @ 3130'. Rigged down Blue Jet. RIH with 2 3/8" tubing. Rigged up BJ. Spotted 100' cement plug on top of CIBP. Pumped 4 bbls of type 3 cement mixed @ 14.5 ppg. Total cement 16 sks. POOH with 2 3/8" tubing.

11/3/99 Rig up Blue Jet, Perf squeeze holes @ 2900' 4 shots, and 4 shots @ 2430'. Rig down Blue Jet. RIH with 2 3/8" tbg and Hallib 7" cement retainer. Set retainer @ 2887'. Rig up BJ to squeeze. Establish rate down tubing, @ 2.3 BPM @ 1445 psi. Well DID NOT CIRCULATE. Pumped 105 sks Class H with fluid loss and cello flakes. Pumped cement @ 15.6 ppg. Displaced to retainer. Stung out of retainer. POOH with 2 3/8" tubing and Hallib setting tool. No indication that cement came around to the top holes.

Pumped on Csg. Casing would not hold pressure, pressure to 500 psi and would lose approx 100 psi in 30 minutes. RIH with 2 3/8" tubing, 6 3/4" bit and 7" casing scrapper. Tagged cement @ 2867'. Drilled cement to 2882'. RIH with 7" Hallib R - 4 packer and 2 3/8" tubing. Set packer @ 2420' and tested casing to 1000 psi - OK. Perfs @ 2430' leaking pumped in @ 1.5 BPM @ 900 psi. Trigon notified BLM @ 599-8907 @ approx 3: 00 PM 11/4/99, about squeeze cement procedure. Pulled up and set packer @ 2168'. Rigged up BJ and squeezed with 50 sks Class H with fluid loss, mixed @ 15.6 PPG. Pumped @ 1 BPM @ 130 psi, pressure increased to approx 1000 psi. Hesitated on squeeze. Displaced to within 50' from top of hole. Shut in with 900 psi on tubing. Rigged down BJ.

11/5/99 Released and POOH with 7" Hallib R-4 Packer set @ 2172', and 2 3/8" tubing. RIH with 6 3/4" bit and 2 3/8" tubing. Tagged top of cement @ 2385' drilled cement to 2415'. Cement not real hard, only 15 hrs since squeeze job. Circulate Clean.

<u>11/8/99</u> Drilled cement from 2415' to 2475'. Drilled out of cement. Tested casing to 700 psi for 30 minutes. Continue to RIH to 2882'. Circulate hole clean. POOH with 2 3/8" tubing with 6 3/4" bit. Rig up Blue Jet and run CBL / Gamma Ray log from 2876' to 50'. TOC @ 200'. Ran CBL log with 500 psi on casing. Perf PC zone with 4 spf @ 2828'-27-26-25-24-23-22-21-20-19-18-17-16-15-14-2813 & 2785-84-83-82-81-80-79-78-77-76-75-2774. All shots 4 spf Total holes 104. Hole size .34" with 14-gram charge.

## CONOCO INC. San Juan 28-7 Unit #10

API #30-039-07223

990' FSL & 1120' FWL, UNIT LETTER "M" Sec. 36. T28N-R7W

Check well, no pressure. RIH with 7" casing scrapper and 2 3/8" tubing. Run scrapper to 2800'. POOH with 2 3/8" tubing and 7" casing scrapper. Change equipment to 3 1/2". Spot float with frac string. Tally and RIH with 3 1/2" frac string and Hallib 7" RTTS packer. Ran total of 82 its 3 1/2" tubing. Set packer @ 2633'. Heated frac tanks to 80 degrees.

Pressure backside to 400 psi. Rig up BJ to acidize and frac. Took rate down tubing, @ 7.7 BPM @ 11/10/99 2600 psi. Bullhead 750 gals of 15% HCL Acid @ 3.5BPM @ 1677 psi. Fraced PC zone with 65,000 # of 20/40 AZ sand with 30,257 gals 30#, 70Q Foam. Total N2 pumped 360,000 scf. Avg pressure 3150 psi @ 30 bpm avg rate. Max pressure 3368 psi. Max sand conc 4 #/ gal. ISIP 2020 psi. 15 min. 1368 psi. Rig down BJ. Started flowing well back with 1/4" choke nipple. Will flow back and test thru the night.

Flowed well thru the night. Flowed well thru 1/4" choke nipple. Avg flowing pressure 650 psi. Installed 1/2" choke nipple. Pressure stabilized @ 150 psi. Tested well as follows: 3 1/2" tubing @ 2633'. MCFPD = 990. Water = 10 bbls. 0 - oil. Tubing pressure 150 psi. Casing pressure 0 psi. (HAS A PACKER). Test witnessed by Victor Barrios with Key Well Service. Released Hallib 7" RTTS packer and POOH with 3 1/2" tubing and packer. Rig up Blue Jet. RIH and set Hallib 7" Fas Drill Plug @ 2764' KB. RIH and perf FC zone @ 2754 - 42, 2728 - 22, 2663 - 58, 2653 - 48, 2643 - 39, 2637 - 34, 2629 - 26, 2576 - 73, 2567 - 63. Shot with 4 spf. Total holes 180. Hole size .32", 11 gram charge. RIH with 3 1/2" frac string with Hallib. 7" packer. Set packer @ 2507'.

Riq up BJ to frac well. With 3 1/2" frac string and Hallib. 7" packer set @ 2507'. Acidized well with 750 gals of 15% HCL acid. Acid was bullheaded ahead of frac. Rate on acid 3 bpm @ 1211 psi. Fraced well with 115,780 # of 20/40 AZ sand. Total fluid pumped 383 bbls of 30# 70 Q foam. Fraced well @ 3350 psi avg pressure @ 40 bpm avg rate. Max pressure 4050 psi. Max sand conc 5# / gal. Total N2 pumped 644,000 scf. ISIP - 2350 psi. 15 min - 1408 psi. Rig down BJ. Started flowing well thru 1/4" choke nipple. Will drywatch and flow well thru the night.

Well still flowing thru 1/4" choke nipple. Tbg pressure stabilized @ 60 psi. Well cleaned up and 11/13/99 quit flowing sand. Csg pressure 0 psi, well has a packer. SHUT WELL IN @ 5:00 PM 11/13/99.

Opened well up and tested well thru 1/2" choke nipple. With 3 1/2" tubing and packer @ 2507'. Tubing pressure stabilized @ 60 psi, with 0 psi casing pressure. (HAS A PACKER). Tested FC Zone @ 396 MCFPD with 4 bbls of water and 0 bbls of oil. Test witnessed by Victor Barrios with Key Well Service. Released and pulled 3 1/2" frac string with Hallib 7" packer. Laid down all 3 1/2" frac string. Started to RIH with 2 3/8" tbg with 7" Baker Metal Muncher Mill.

Check well pressures, 1000 psi. Blow well down; continue to RIH with 2 3/8" tubing with Baker Metal Muncher Mill. Tagged sand @ 2740', rigged up power swivel, and BJ Nitrogen. Cleaned sand to Hallib Fas Drill Plug @ 2764'. Drilled up Hallib Fas Drill Plug @ 2764'. Continued in hole to 2784'. Well making heavy sand and water. Pulled up to 2161' KB. Will Rig up Blowie Line.

Rig up Blowie Lines to continue to allow well to clean up. RIH with 2 3/8" tubing with Baker Metal 11/17/99 Muncher Mill. Tagged sand @ 2784'. Rigged up BJ Nitrogen. Cleaned sand from 2784' to PBTD @ 2882'. Pumped 2 soap sweeps to allow well to clean up. Pulled tubing above perfs.

Check wellhead pressures. Csg - 820 psi. POOH with 2 3/8" tubing with Baker Metal Muncher Mill. 11/18/99 RIH with Mule Shoe Collar, SN and 2 3/8" tubing. Tagged fill @ 2872' for 10' of fill. Pulled up to 2668'. Flowed well up the tubing, to allow well to clean up. Flowed well thru the night with 1/2" choke nipple.

Well flowed thru the night with 1/2" choke nipple. With 2 3/8" tubing @ 2670' tubing pressure 11/19/99 stabilized @ 170 psi. Csg - pressure 220 psi. MCFPD = 1122. Water - 7 bbls. Oil - 0 bbls. Test witnessed by Victor Barrios with Key Well Service. This flow rate is for the FC & PC zones combined. Run in hole to tag for fill. Tagged fill @ 2869'. Bottom perf @ 2828'. Pulled up and landed 2 3/8" tubing @ 2639' with KB added in. Total 2 3/8" tubing 85 jts. Seating nipple & Mule Shoe Collar on bottom. NDBOP & NUWH. Rig down and move off location, FINAL REPORT