

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ **Recomplete Temporarily Abandoned Well**

2. NAME OF OPERATOR
Davis Drilling, Inc.

3. ADDRESS OF OPERATOR
P.O. Box 757, Great Bend, Kansas 67530

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

**1785' from North Line
1840' from East Line of Sec. 26-28N-1W**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7194 RT 7205

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache #240

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Boulder Lances

11. SEC., T., E., M., OR BLK. AND
SURVEY OR AREA

**SE 1/4
26-28N-1W**

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) **Recomplete Temp. Abandoned Well**

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

**4/27/74 Pull liner (557' 4" FD set 4325)
8/24/74 Move in cable tools
8/25/74 Clean out hole to TD. Well started making oil 300' off bottom
8/28/74-9/3/74 Drill cuttings & test
9/4/74 Run 2 3/8" tubing to 4240'
9/5/74 Run rods. Hook up unit & put on pump. Oil surface in 2 1/2 hrs.
Start in tank 7:30 p.m.
9/6/74 Testing. Well made 1060 / 12 hrs.
9/7/74 Well pump 960 / 24 hrs.
9/8/74-9/15/74 Well pump av. 7.5 bopd - gas lock
9/19/74-9/25/74 Well av. 15.5 bopd
Complete av. 15 bopd. File Form L-104 with State**



18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

President, Davis Drilling, Inc.

DATE

9/27/74

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

21

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are any applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for special instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking for approval of the abandonment.