COPY FOR
STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
SUBMIT IN TRIPLICATE TO
DISTRICT OFFICE

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office_	Santa Fe
Lease No	078498
Unit	H. Hickson

## SUNDRY NOTICES AND REPORTS ON WELLS

	TENTION TO DRILL	\ <del></del>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INT	TENTION TO CHANGE PLANS			1
	TENTION TO TEST WATER SHUT-	į	SUBSEQUENT REPORT OF ALTERING CASING	•
	TENTION TO RE-DRILL OR REPA		SUBSEQUENT REPORT OF REDRILLING OR REP	
NOTICE OF INT	TENTION TO SHOOT OR ACIDIZE	\$200	- 3050240211 112 0111 01 12 12 12 12 12 12 12 12 12 12 12 12 12	
NOTICE OF INT	FENTION TO PULL OR ALTER CA	\SING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF IN	TENTION TO ABANDON WELL			· i
	(INDICATE ABOVE BY		URE OF REPORT, NOTICE, OR OTHER DATA	
		•••	August 10,	
NE/1 of Sec.	and Sec. No.)	(1 <del>w</del> p.)	Range)  Range)  (State of No.	
	• •			intory)
he elevation	on of the derrick floor	above sea leve	l is ft.	
		DETAIL	S OF WORK	
	of and expected depths t	<b>DETAIL</b>		roposed casings rk)
Drill Me Drill Po Set 300 Set 7° 0	of and expected depths to indicate muddling jobs, sa Verde test with int lookeut sand a feet 13-3/8 OD is	DETAIL to objective sand, cementing point	S OF WORK  ds; show sizes, weights, and lengths of p	eand.
Drill Ne Drill Po Set 300 Set 7° 0 Estimate	sof and expected depths to indicate muddling jobs.  sa Verde test with int lookeut sand a feet 13-3/8 OD in the casing of TD 5000 feet.  stand that this plan of wo ons may be commenced.	DETAIL to objective sand cementing poin a retary technical complete to make case y on Point I	S OF WORK  ds; show sizes, weights, and lengths of p ts, and all other important proposed wo  ls to top of foint leokout a th cable tools.  ding at 300 feet commented to	surface. O sacks.
Drill No. Drill Por Set 300 Set 7° 0 Estimate  I undersoperation	sof and expected depths to indicate muddling jobs, as Verde test with int lookeut sand a feet 13-3/8 OD is 18-3/8 OD is 18	DETAIL to objective sand cementing poin a retary technical complete to make case y on Point I	dis; show sizes, weights, and lengths of posts, and all other important proposed wo like to top of Point Lookout and the cable tools.  Sing at 300 feet commented to content and commented with 300 contents and commented with 300 contents.	surface. O sacks.
Drill No. Drill Por Set 300 Set 7° 0 Estimate  I undersoperation	sa Verde test with and lookent sand a feet 13-3/8" OD la test with a sand a feet 13-3/8" OD la test.  Stand that this plan of wo ons may be commenced.  Byrd-Frost, Inc.	DETAIL to objective sand, cementing point testary tector and complete testary tector testary testary tector testary test	dis; show sizes, weights, and lengths of posts, and all other important proposed wo like to top of Point Lookout and the cable tools.  Sing at 300 feet commented to content and commented with 300 contents and commented with 300 contents.	sarface.  Sarface.  Sarface.  Survey before