Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5.	Lease Serial No.
	SFSF079521

SUNDRY Do not use the abandoned we	SFSF079521 6. If Indian, Allottee or Tribe Name					
SUBMIT IN TRI	If Unit or CA/Agreement, Name and/or No. SAN JUAN 28-5 UNI					
Type of Well ☐ Oil Well	1991			8. Well Name and No. SAN JUAN 28-5 UNIT 41		
2. Name of Operator BURLINGTON RESOURCES	PEGGY COLE E-Mail: pbradfield@br-inc.com			9. API Well No. 30-039-07276		
3a. Address 3401 EAST 30TH FARMINGTON, NM 87402	3b. Phone No. (include area code) Ph: 505.326.9727 Fx: 505.326.9563			10. Field and Pool, or Exploratory BLANCO MV/BASIN DK		
4. Location of Well (Footage, Sec., 7	n)			11. County or Parish,	and State	
Sec 32 T28N R5W NENE 815				RIO ARRIBA COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE I	NATURE OF 1	NOTICE, RI	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
- Nation of Intent	☐ Acidize	☐ Deep	en	☐ Product	ion (Start/Resume)	☐ Water Shut-Off
☐ Notice of Intent	☐ Alter Casing	☐ Fract	ire Treat	☐ Reclam	ation	■ Well Integrity
Subsequent Report	☐ Casing Repair	□ New	Construction	□ Recomp	olete	⊠ Other
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug	and Abandon	☐ Tempor	arily Abandon	Subsurface Commi
	☐ Convert to Injection	☐ Plug	Back	☐ Water I	Disposal	8
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involve testing has been completed. Final A determined that the site is ready for 10-17-01 MIRU. ND WH. NU 10-18-01 TOOH w/184 jts 2 3 assembly stuck in pkr. Chemi 10-19-01 Repair rig. TIH w/fis 10-20-01 Fishing. SD for wee 10-22-01 TOOH w/224 jts topkr @ 7130'. Circ hole clean. 10-23-01 Establish circ. Mill CIBP. CIBP stuck. TOOH. TIH 10-24-01 Fishing. Left CIBP perf Cliff House w/1 SPF @ 5215, 52	ork will be performed or provided operations. If the operation is bandonment Notices shall be final inspection.) BOP. TOH w/10 jts 2 3/8/8/8" tbg. Attempt to screw cal cut tbg @ 7120'. TOC shing tools. SDON. Exercise shall be	the Bond No. or results in a multiplified only after all sided only after a sid	er. TOOH. TIH w/pkr tool. Mil H, ran CCL log EIBP, set @ 55 0.3" diameter 5, 5368, 5388	IA. Required secompletion in auding reclamation with the point. I out Model "g. TIH w/7" 22'. TOOH. holes total., 5400, 5423	ubsequent reports shall be a new interval, a Form 3 ion, have been completed. Seal TIH, Perf , 5430,	be filed within 30 days 160-4 shall be filed once
, ,	Electronic Submission For BURLINGTON R Committed to AFM	RESOURCES OII SS for processi	& GAS, sent to ng by Lucy Bee	to the Farmin on 11/16/200	gton)1 ()	
Name (Printed/Typed) PEGGY C		Title REPORT AUTHORIZER				
Signature (Electronic	tronic Submission) Date 11/13/2001					
	THIS SPACE FO	OR FEDERAL	OR STATE	OFFICE U		
Approved By			Title		AU LET II Date	ed For Record
Conditions of approval, if any, are attach certify that the applicant holds legal or ec which would entitle the applicant to cond	es not warrant or he subject lease	Office		N	2 1 2001	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or series of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #8913 that would not fit on the form

32. Additional remarks, continued

- 5440, 5461, 5484, 5499, 5509' w/36 0.3" diameter holes. TOOH. TIH w/RBP, set @ 5010'. Load hole w/200 bbl 2% KCl wtr. Ran CBL-CCL-GR @ 1900-5010', TOC @ 1900'. SDON. 10-25-01 TIH w/pkr, set @ 65'. TOOH. Load hole w/wtr. PT csg to 3000 psi/15 min, OK. TIH w/retrieving tool. Blow well & CO. Latch RBP @ 5010'. TOOH. TIH w/7" pkr. PT CIBP to 3000 psi/15 min. OK. TOOH w/pkr. Acidize w/15 bbl 15% HCl. Displace w/25 bbl 2% KCl wtr. SDON. 10-26-01 TOOH. TIH, frac Cliff House/Menefee w/835 bbl slk wtr, 648,918 SCF N2, 50,000# 20/40 Brady sd. TOOH, SDON. 10-27-01 TIH w/CIBP, set @ 4924'. Load hole w/142 bbl 2% KCI wtr. PT CIBP to 3000 psi, OK. TOOH. TIH, perf Lewis w/1 SPF @ 4329, 4332, 4337, 4358, 4360, 4363, 4374, 4384, 4392, 4425, 4504, 4510. 4512, 4516, 4520, 4524, 4530, 4537, 4543, 4564, 4573, 4587, 4605, 4650, 4690, 4705, 4728, 4747, 4763, 4786, 4800, 4814, 4833, 4846, 4894 w/35 0.3" diameter holes total. Acidize w/30 bbl 15% HCl. Displace w/77 bbl 2% KCl wtr. Frac Lewis w/738 bbl 20# linear gel. 1.329.269 SCF N2, 200.000# 20/40 Brady sd. CO after frac. 10-28-01 Blow well & CO. 10-29-01 TOOH, TIH w/3 7/8" mill to 3326'. Blow well & CO. Mill out CIBP @ 4924'. TIH. blow well & CO. 10-30-01 TIH, blow well & CO. Attempt to mill out CIBP @ 5522'. TIH, blow well & CO. 10-31-01 TOOH w/mill. Lost 6 drill collars in hole. TIH w/fishing tools. Fishing. 11-1-01 Fishing. 11-2-01 Fishing. TOOH w/fish & fishing tools. Left 2 blades of mill in hole. TIH w/mill to 5436'.
- Blow well & CO to 5446'. SDON. 11-3-01 Blow well & CO. Mill on CIBP @ 5522'. SD for weekend.
- 11-5-01 Mill out CIBP @ 5522'. TIH, mill on CIBP @ 5641'.
- 11-6-01 Mill on CIBP @ 5641'. SDON.
- 11-7-01 Mill out CIBP @ 5641'. TIH, blow well & CO to PBTD @ 7816'. TOOH w/mill.
- 11-8-01 TIH w/246 jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 7706'. (SN @ 7705'). ND BOP. NU WH. RD. Rig released.

Well will produce as a Mesaverde/Dakota commingle under DHC-2050.