## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Not:	ices and Reports on Wells	F:1 2: 43
1. Type of Well GAS		Lease Number SF-079050-B If Indian, All. or Tribe Name
2. Name of Operator  BURLINGTON  RESOURCES	DEC .	2 100 7. Unit Agreement Nam San Juan 28-6 Unit
3. Address & Phone No. of Opera PO Box 4289, Farmington, NM		8. Well Name & Number San Juan 28-6 U #1 9. API Well No.
4. Location of Well, Footage, S 790'FSL, 1850'FWL, Sec.26, T	ec., T, R, M	30-039-07283  10. Field and Pool Basin Dakota / N V  11. County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO IN  Type of Submission  _X_ Notice of Intent  Subsequent Report	Type of Action Abandonment X Recompletion Plugging Back Casing Repair	REPORT, OTHER DATA  on  Change of Plans  New Construction  Non-Routine Fracturing  Water Shut off  Conversion to Injection
13. Describe Proposed or Comp  It is intended to recompl		rding to the attached procedure.
	Title Regulatory Admi	nistrator Date 11/15/99
(This space for Federal or State APPROVED BY CONDITION OF APPROVAL, if any:	te Office use) Title	Date 14/25/99

ch) e

District I PO Box 1980, Hobbs, NM 88241-1980 District II

District III

State of New Mexico
Energy, Minerais & Natural Resources Department

Form C-102

Revised February 21, 1994

Instructions on back Submit to Appropriate District Office

State Lease - 4 Copies

OIL CONSERVATION DIVISION Subsequence PO Box 2088 Santa Fe, NM 87504-2088 22 71 2: 43

Fee Lease - 3 Copies

District IV PO Box 2088, Santa Fe, NM 87504-2088

PO Drawer DD, Artesia, NM 88211-0719

1000 Rio Brazos Rd., Aztec, NM 87410

AMENDED REPORT

## WELL LOCATION AND ACREAGE DEDICATION PLAT <sup>3</sup> Pool Name <sup>2</sup> Pool Code API Number 72319/71599 Blanco Mesaverde/Basin Dakota 30-039-07283 ' Well Number Property Name Property Code 113 San Juan 28-6 Unit 7462 ' Elevation Operator Name 'OGRID No. 6617' GR Burlington Resources Oil & Gas Company 14538 10 Surface Location Fast/West line County North/South line Feet from the Feet from the Section Township Range Lot Idn UL or lot no. 1850. Wast 26 28N 790 South 11 Bottom Hole Location If Different From Surface Feet from the East/West line County Feet from the North/South line Lot Ida Range UL or lot no. Section Township 12 Dedicated Acres 13 Joint or Infill 14 Consolidation Code 15 Order No. W/320NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION 17 OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief Original plat from E.V. Echohawk 9-11-63 Signature Printed Name Regulatory Administrato Title Date 18SURVEYOR CERTIFICATION I hereby cerafy that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief. Date of Survey Signature and Seal of Professional Surveyer: 1850 Certificate Number

## SUNDRY NOTICE SUBMITTAL

Well: San Juan 28-6 Unit #113

Unit N. Sec. 26, T 28N, R 6W

Rio Arriba, NM

It is intended to recomplete the Mesaverde formation in the existing Dakota wellbore. A rig will MIRU, ND wellhead, NU BOP, and pull production tubing. A CIBP will be set above the Dakota formation at approximately 6092'.

If adequately isolated by cement, the Mesaverde will be perforated and fracture stimulated in three stages in the following interval: 4000' - 5992' . If cement remediation operations are necessary, Burlington Resources will contact the appropriate regulatory agency for approval prior to work initiation.

After stimulation flowback, the CIBP above the Dakota will be drilled out and tubing will be landed approximately 100' above PBTD. The well will then produce commingled production for the Mesaverde and Dakota formations. Application for commingling will be submitted.

Approved: Bruce D. Bony 11-10-99
Drilling Superintendent Date