UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	a para a servicio de la companio del companio de la companio del companio de la companio della companio de la companio della c		
Sundry Not	ices and Reports on Wells		-
Type of Well GAS	DECETIVED OCT 1 1 1994	5. 6.	Lease Number SF-079519A If Indian, All. or Tribe Name
Name of Operator MERIDIAN OIL	OIL COM. DIV.	7.	Unit Agreement Name San Juan 28-5 Unit
	DISIL 3	8.	Well Name & Number
Address & Phone No. of Opera PO Box 4289, Farmington, NM		9.	San Juan 28-5 U #49 API Well No. 30-039-07386
Location of Well, Footage, S	ec., T, R, M	10.	Field and Pool
1550'FNL, 950'FEL, Sec.23, T-28-N, R-5-W, NMPM		11.	Blanco Mesaverde County and State
			Rio Arriba Co, NM
Set CIBP @ 655 3800 psi, OK. good cmt bond 9-26-94 Frac Menefee w/8 House @ 6192-6 9-27-94 Frac Cliff House 9-28/30-94 Blow well & C	Casing Repair Water Altering Casing Constructions Nother - pay add Constructions BOP. TOOH w/218 jts 2 3/8" tbut of the construction of the con	g. Ran 4 586'. PT H. Ran CB 37-6528' bbl 20# l	o Injection 1/2" gauge ring to 656 CIBP, 4 1/2" csg & tbg L-CCL-GR @ 6550-4562', w/68 holes. RD. inear gel. Perf Cliff r gel. CO after frac.
			RECEIVER N
. I hereby certify that the	e foregoing is true and correc	t.	<u>≈ </u>
gned Japan Stall huis	Title Regulatory Affairs	Date 1	0/4/94
his space for Federal or Stat			DIED COB SECOND
PROVED BY NDITION OF APPROVAL, if any:	Title	Date _	DOT 0 5 1994

FARMINGIUM GISINIL, JEFICE