

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well

GAS

2. Name of Operator

MERIDIAN OIL

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1335' FNL, 870' FEL, Sec.29, T-28-N, R-4-W, NMPM

5. Lease Number

NM-03863

6. If Indian, All. or

Tribe Name

7. Unit Agreement Name

San Juan 28-4 Unit

8. Well Name & Number

San Juan 28-4 U #37

9. API Well No.

30-039-20673

10. Field and Pool

Basin Dakota

11. County and State

Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☒ Notice of Intent☐ Abandonment☐ Change of Plans☐ Subsequent Report☐ Recompletion☐ New Construction☐ Final Abandonment☐ Plugging Back☐ Non-Routine Fracturing☐ Casing Repair☐ Water Shut off☐ Altering Casing☐ Conversion to Injection☒ Other - Pay add

13. Describe Proposed or Completed Operations

It is intended to add pay to the Dakota formation of the subject well in the following manner:

Trip out of hole with tubing. Selectively reperforate the Dakota interval. Fracture stimulate the Dakota with sand and gelled water. Clean out to plug back total depth after fracture treatment. Rerun tubing. Return the well to production.

14. I hereby certify that the foregoing is true and correct.

Signed

Peggy Shadwick

(SHL8) Title Regulatory Administrator Date 2/20/96

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

Date

CONDITION OF APPROVAL, if any:

APPROVED

FEB 23 1996

DISTRICT MANAGER

NMOC